

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	MMP PACKETIS SAS ACU231313 M. Loïc Peyronnet Treille 16380 Chazelles France +33 5 45 38 20 03 / +33 6 44 23 34 08 loic.peyronnet@mm.group
---	--

Ticket number:	E2164
Customer order:	CDE CLIENT 2078474
Machine customer name:	SHS4000
Tiket type:	INTERVENTION
Assign to:	CouV -> vivien.Coutellier@bst.group
Ticket date:	2024/07/16
Material:	VIDEO_SHS4000
Type:	
SN:WA:	
Installation date of material:	
Teamviewer:	
PC model:	
Original Application Version	

2 day(s) of intervention calculation

2024 / 2024	Mon.05/08	Tue.06/08
Drive time	5	0.5
AM Start	14:00	08:00
AM End		
PM Start		
PM End	17:30	11:00
Drive time	0.5	4.5

Start date of intervention	2024/08/05-14:00
End date of intervention	2024/08/06-11:00
Reason:	
Actions:	SHS 4000 : The wiring of the format signal was bad and needed to be remade EKR 1000 : The connector of the sensor 2 need to be repaired, the sensor 1 was switched
Remarks:	
Ticket status:	open

Comment(s)


(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Tentative de réparation du connecteur du capteur 2, pas de facturation si réparation impossible.

Customer signature:

Name:

Date :




06/08/2024 11:30

BS

ST eltromat FRANCE signature:

Name:

Date :



06/08/2024 11:21

ATTACHED CALL'S FILE(S)

[CDE CLIENT_2078474](#)

--	--	--