

Intervention
On Customer Site

Visit Report

Reference :

Commande BSTe France : 202208		Call / PM number : E877	
Customer :	Amcor Flexibles (DIJON)	System :	Regi_Star 20
Customer Contact :	Alexandre WARASKA	SN :	ASO0071527_WA0021342
Customer Order number :		Machine Nickname :	i33

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☒
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☒ Yes				
	☐ No				

	23/08 /2020	24/08 /2020	25/08 /2020	26/08 /2020	27/08 /2020	28/08 /2020
Travel To		3h30	0.25	0.25	0.25	
Start Time	-	11h00	8h20	8h20	8h00	
Lunch Time	-	0.25	0.5	0,5	0.5	
End Time	-	19h00	19h10	18h00	15h30	
Travel From	-	0.25	0.25	0.25	3h30	

Details	Startup, commissioning, finetuning, adjustment, instructions de service. Operator want an alarm: "mark alarm" beckhoff -3000A1 out (8"signal" and 7 "GND") when marks are out of gate - Encoder position is OK. - Mechanically: PU6 should be little bit down, to have read fiber on the roller to have a more stable reading.
---------	--

Intervention

On Customer Site

	• On PU7: traverse need to be higher. • E-stop should be connected (photo in annexe) • Acceleration signal must be connected
--	--

Purpose of the visit completed : Yes ☐ No ☒Need a new visit : Yes ☒ No ☒

Customer details for REGISTAR 20 Systems

Customer name and place : [Amcor Flexibles DIJON](#)

Contact person at customer : Alexandre Waraksa

Customer Mail & Mobile/Landline : [Alexandre Waraksa <alexandre.waraksa@amcor.com>](mailto:alexandre.waraksa@amcor.com)System Type : [Regi_Star 20](#)

ASO/WA : ASO0071527_WA0021342



Machine Manufacturer/Model/Nickname : Cerutti /i33

Date : 26/08/2021

Name : [Jean-Baptiste Nguyen](#)

Comments :

Signatures :


   26/08/21 -



Intervention

On Customer Site

Technical datas

Notes



Intervention

On Customer Site




Intervention

On Customer Site




Intervention

On Customer Site




Intervention

On Customer Site



Intervention

On Customer Site



Intervention

On Customer Site

