

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Livcer M. Charles de Livonnière 593 avenue Blaise Pascal - Lotissement Anaconda 2 77550 Moissy Cramayel France charles.livonniere@livcer.com
--	---

Preventive reference number	PMREPORT-337_PM977_2025-09-30
Contract number / Numéro de contrat	CM2408065
Contract date:	2024/09/01 -> 2027/08/31
Machine customer name:	P4
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 1100 7200 / M2051dC 0.1667
SN:WA:	ASO089565_50.2649
Origin BST France order:	222010
Installation date of material:	2023/09/12

TECHNICAL DATAS

PC MODEL	Optiplex 7090 / Tag CTSQYR3
PC NAME	TubeScan502649
ADDITIONAL CAMERA INFO	TubeScan DS 1100 7200 / M2051dC 0.1667
OPERATION SYSTEM	Windows 10 Pro / v22H2
MEMORY RAM	32 GB
FREE SPACE ON C	97.9 / 237 GB
FREE SPACE ON D	Q:\ 3.44 / 3.63 TB
TEAMVIEWER ID	1 011 259 725 / v15
IP ADDRESS EXTERN FOR INTERNET	DHCP Automatic
ORIGINAL VERSION	7.4.61.23532
UPGRADE OR DOWNGRADE VERSION LAST INTERVENTION	8.0.42.36731 hot fix8 from E2622
UPG OR DNG VERSION DURING MAINTENANCE	8.0.42.36731.hotfix-11

Start time PM:	30/09/2025 11:00
End time PM:	30/09/2025 13:30

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024X768	Encoder wheel status	✓	
View monitor resolution		2560X1440	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	✓	
PC's fans ?	II		Date UPS's batteries exchanged ?		2022/02/01
PC's filter	II		Installation date:		2023-09-12 -> 03 YEAR(S)
Lens cleaning	✓		UPS communication?	✓	
Mirror cleaning	✓		Softwareworkflowcommunication	✓	On QLink
Backing or RRB cleaining	II	Missing Barking Bar	Check Teamviewer access	✓	1 011 259 725 / v15
Lens Focal	✓		Calibration of camera detail & 100%camera	II	
Camera alignment with printing	✓		Operators instruction ?	✓	
Check web under camera	✗	Curves on edges	Screenshots	✓	On 8.0.42.36731.hotfix-11
Height compensator calib	✓		ACRONIS ?	✗	
Encoder offset calib	✓		Backup application	✓	On 8.0.42.36731.hotfix-11
Only with EV- LED calibrations	II				
Kisspoint only with 2 cameras	✓				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- ✓ ENCODER WHEEL:: 2RDHO234275
- ✓ LED Board equipped V40 L=140mm: 1ELLT256485
- ✓ LED Board equipped V40 L=160mm: 1ELLT256486
- ✓ ENCODER'S SPRING
- ✓ BACKPLATE W/B

- ✓: Checked, nothing to report / Vérifié, RAS
- ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
- ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance Done
- Software upgrade to v8.0.42.39529.hotfix-11
- UPS Battery need to be replace on Q2/2026
- Missing Backing Bar

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :



01-Oct-25 3:59 PM



01-Oct-25 3:59 PM

ATTACHED PM'S FILE(S)

Picture 30092025	Screenshot 30092025
	