

On Customer Site

Visit Report

Reference :

Commande BSTe France :		Commande BSTe Int. :	
Customer :	ADAPA SCHUR FLEXIBLES Uni Packaging AVERDOINGT	System :	wvstar_2000
Customer Contact :	Aurélien Gervois	SN :	WA18482
Customer Order number :		Machine Nickname :	ROTO09

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☒	Under Contract	☒	Out of Contract	☐
Troubleshoot	☒	Under Warranty	☐	Out of Warranty	☐
Instruction	☐ Yes				
	☒ No				

Details	Remplacement des Flash bulb et nettoyage du connecteur. Le câble RJ45 de la caméra est a remplacer par un câble RJ45 Cat 7.
---------	---

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

Maintenance Checklist for IPQ Systems

Available supporting documents :

- Check list for maintenance

Customer name and place : ADAPA SCHUR FLEXIBLES Uni Packaging AVERDOINGT

On Customer Site

Address	Hameau de Neuville Planque
Zip	62127
City	Averdoingt
Country	France

Contact person at customer : M. Aurélien Gervois

Customer Mail & Mobile/Landline : nicolas.fournier@ceeschisler.fr / +33 7 72 24 33 25

System Type : webvideo_star 2000

SN :
WA18482


Machine Manufacturer/Model/Nickname : : Roto 9
Date : 17/10/2024

Name : Coutellier Vivien


Comments :

Replacement of the 8 flashbulb of the matrix camera.

Signatures :



BST eltromat FSE



Customer
A. Gervois

On Customer Site

Prior to a Preventive Maintenance :

Check for system affecting modification reports and software releases.

Check for optional light source.

Check with customer about problems, or failure with the system.

1. Cleaning the optical parts :

OK/NOK/NA

- Mirror cleaned with lens wipes.
- Camera lens cleaned with lens wipes.
- Reflectors cleaned with soft cloth using iso propanol or alcohol.
- Backing Bar cleaned with soft using iso propanol or alcohol.
- Optionally acryl insert of backing bar replaced.

☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☐	☒	☐

2. Check functioning of the LEDs :

OK/NOK/NA

- LEDs checked.
- Brightness and uniformity of the image checked.

☒	☐	☐
☒	☐	☐

3. Replacement of the encoder wheel :

OK/NOK/NA

- Encoder wheel replaced and tightened
- Spring replaced (if necessary) and spring force checked (ca. 1kg/10N)

☐	☒	☐
☐	☒	☐

4. Software update :

OK/NOK/NA

- Software Update (if necessary).

☐	☒	☐
--------------------------	-------------------------------------	--------------------------

Old SW version :

New SW version :

5. Final check of the running system :

OK/NOK/NA

- Stability of live image checked (without reference image).
- Stripe alignment checked (Normal and reflective mode).
- Registration checked.

☒	☐	☐
☒	☐	☐
☒	☐	☐

On Customer Site

- | | |
|---|---|
| - Maximum speed checked. | ☐ ☒ ☐ |
| - Stable location of the EagleView camera checked. | ☐ ☐ ☒ |
| - Hard drive capacity checked. | ☒ ☐ ☐ |
| - Backup created and saved locally and/or on USB stick. | ☒ ☐ ☐ |

6. Backup :

OK/NOK/NA

- | | |
|--------------------------------------|---|
| - IPQ Backup folder | ☒ ☐ ☐ |
| - IPQ screenshot folder | ☒ ☐ ☐ |
| - WindowsImageBackup and/or Image | ☐ ☒ ☐ |
| - Application / Computer Screenshots | ☒ ☐ ☐ |

Parts replaced during Preventive Maintenance :

- | | |
|-----------------------------------|-----|
| 1 - 8 FlashBulb for matrix camera | 3 - |
| 2 - | 4 - |

Parts suggested to replace during the next Maintenance :

- | | |
|-----|-----|
| 1 - | 3 - |
| 2 - | 4 - |

Part need to be replaced as soon as possible :

- | | |
|-----|-----|
| 1 - | 4 - |
| 2 - | 5 - |

On Customer Site

Technical datas

Computer name :

Total Physical Memory : 16 GB

Free Space in C Drive (System) : 203 GB

OS : Windows 7 Pro

Screen Resolution Touch :

Screen Resolution Full View : 1920*1080

Computer Model :

Date :

Remote Maintenance (Teamviewer)

IP address : DHCP Auto

Subnet mask :

Default gateway :

Preferred DNS server :


Alternate DNS server :

Teamviewer ID / Version :

943958422

On Customer Site

Notes



A. Gerwold

Je 17/10/2024