

On Customer Site

Visit Report

Reference :

Commande BSTe France : CM2305054		Call / PM number : PM591	
Customer :	Logre Imprimeurs	System :	Inspection System
Customer Contact :	M. Claude Tina Ndongo	SN :	426902
Customer Order number :		Machine Nickname :	BOBST M5

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☒	Under Contract	☒	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☐ Yes				
	☒ No				

	06/12/2023					
Travel To	2					
Start Time	13h30					
Lunch Time	0					
End Time	17h00					
Travel From	1					

Details	Computer Clean-up Soft and Hard. Archive + Ghost reloading. Cabling checked. Fans, BIOS... Calibration (FOV,Gain,Offset...)
---------	---

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Maintenance Checklist for NYQUIST Systems

Available supporting documents :

Customer name and place : [Lorge Imprimeurs / 6 Rue Yves Toudic – 69200 – Vénissieux, France](#)

Contact person at customer : [M. Claude Tina Ndongo \(Chef d'équipe\)](#)

Customer Mail & Mobile/Landline : claudetina.ndongo@lorge.fr / +33 7 71 43 85 86

System Type : [Helios S 430 mm](#)

SN : [426902](#)

Machine Manufacturer/Model/Nickname : [BOBST / M5 430 8K / BOBST](#)

Date : [07/12/2023](#)

Name : [Arnaud Darcel](#)

Comments :

Signatures :

BST eltromat FSE

Customer

On Customer Site

Prior to a Preventive Maintenance :

Check for system affecting modification reports and software releases.

Check for optional light source.

Check with customer about problems, or failure with the system.

1. Cleaning the optical parts :

OK/NOK/NA

- Mirror cleaned wit ZEISS lens wipes. ☒ ☐ ☐
- Camera lens cleaned with ZEISS lens wipes. ☒ ☐ ☐
- Reflectors cleaned with soft cloth using iso propanol or alcohol. ☒ ☐ ☐
- Back plate cleaned. ☒ ☐ ☐
- Computer filter cleaned/~~replaced~~ ☒ ☐ ☐

2. Camera calibration :

OK/NOK/NA

- Field of View / Period 10.05 : 427.00 mm ☒ ☐ ☐
- Offset/Gain Calibration. ☒ ☐ ☐
- Zero LED calibration : Anyspeed & Position : (Virtual) ☐ ☐ ☒

3. Check functioning of the Lamps :

OK/NOK/NA

- Lamps replacement. : LED ☐ ☐ ☒
- Brightness and uniformity of the image checked. ☒ ☐ ☐

4. Replacement of the encoder wheel :

OK/NOK/NA

- Encoder wheel ~~replaced~~ and tightened ☒ ☐ ☐
- Spring replaced (if necessary) and spring force checked (ca. 1kg/10N) ☒ ☐ ☐

5. Software update :

OK/NOK/NA

- Software Update (if necessary). ☐ ☒ ☐

Old SW version : 6.0.0.3

New SW version :

On Customer Site

6. Final check of the running system :

OK/NOK/NA

- Stability of live image checked (without reference image).
- Stripe alignment checked (Normal and reflective mode).
- Registration checked.
- Maximum speed checked.
- Hard drive capacity checked.
- Backup created and saved locally and/or on USB stick.

☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☐	☒	☐

7. Backup :

OK/NOK/NA

- BackupRestore
- Archive Printflow

☒	☐	☐
☒	☐	☐

Parts replaced during Preventive Maintenance :

- 1 -
- 2 -

Parts suggested to replace during the next Maintenance :

- 1 -
- 2 -

Part need to be replaced as soon as possible :

- 1 -
- 2 -

On Customer Site

Technical datas

Computer name : [AVT-M5](#)

Total Physical Memory : [16 GB](#)

Free Space in C Drive (System) : [193 GB](#)

Free Space in D Drive : [125 GB](#)

Free Space in E drive (DOS) :

Free Space in F drive (Backup) : [585 GB](#)

OS : [Windows Embedded Standard SP1](#)

Screen Resolution Touch : [1920x1080](#)

Computer Model :

Date :

ACB Firmware : [49/49](#)

Remote Maintenance (Teamviewer)

IP address : [Automatic IP via MAC 00-0B-AB-E7-4B-9C](#)

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : [1 116 979 919 / v15](#)

On Customer Site

Notes
