

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	BBC CELLPACK Packaging ACU231328 M. Laurent Keller 20 Rue Bumkirch - BP20 68720 Illfurth France +33 3 89 68 79 73 laurent.keller@cellpack.com
--	--

Preventive reference number	PMREPORT-348_PM990_2025-10-27
Contract number / Numéro de contrat	CM2309055
Contract date:	2023/10/01 -> 2026/09/30
Machine customer name:	i71
Assign to:	RelR
Material:	VIDEO_IPQ_View
Type:	iPQ View R/V
SN:WA:	ASO101171_WA0022815
Origin BST France order:	232317
Installation date of material:	2024/02/12

TECHNICAL DATAS

PC MODEL	beg-BKA-BSTE05
PC NAME	22815-IPQ-1
ADDITIONAL CAMERA INFO	iPQ View R/V
OPERATION SYSTEM	Windows 10 Enterprise LTSC / 2018
MEMORY RAM	16 GB
FREE SPACE ON C	70.8 / 99.9 GB
FREE SPACE ON D	F: 392 / 394 GB
TEAMVIEWER ID	1 378 156 515 / v15
IP ADDRESS EXTERN FOR INTERNET	DHCP Automatic
ORIGINAL VERSION	3.1.1
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	27/10/2025 15:45
End time PM:	

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization		
Pcscreenresolutiontouch		1920x1080 - 24" (Touch)	Ipqencoderwheelfixing	⏸	
Pcscreenresolutionview		1920x1080 - 23" (View)	Ipqencoderwheelstatus	⏸	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	⏸	
Hardwareconditioncables	✓		Alarmstatusindicator	⏸	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	✓	Default batterie.Changed by customer
Digitalcheckfan	✓		Upsdatebatteryexchanged		2025/10/28
Digitalreplacefilter	✓		Installation date:		2024-02-12 -> 00 YEAR(S)
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	✓	Cam 1 changés Cam 2 OK. Sur Cam 1 Bloc d'alimentation defectueux 2 flash sur 4.Bloc a changer a la prochaine maintenance.	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.13
Camerachangefiltercheckfan	✓		Softwareipqwsc		1.9.7
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	✓		Softwareipqli		-
Traversewscameracheckcleanmirrorlackercamera	✓		Softwareworkflowcommunication	⏸	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	⏸	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
			Backupsoftware	✓	

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:


Name:


Date :

BST eltromat FRANCE signature:

Name:

Date :


28/10/2025 14:58


06/11/2025 09:14

ATTACHED PM'S FILE(S)

[Filtres Cam 1](#)



[Filtres cam 2](#)

