

On Customer Site

Visit Report

Reference :

Commande BSTe France : CM1912025 / 2		Call / PM number : PM427	
Customer :	CPC Cotentin	System :	Jupiter
Customer Contact :	M. Emmanuel Cornu	SN :	307017
Customer Order number :	CM1912025 / 2 signed	Machine Nickname :	Cerutti

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☒	Under Contract	☒	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☐ Yes				
	☒ No				

	18 / 01 / 2023					
Travel To	0					
Start Time	16h00					
Lunch Time	0					
End Time	17h00					
Travel From	0					

Details	Maintenance Préventive du système d'inspection Jupiter sur presse Cerutti. Archivage. Nettoyage des optiques et calibration.
---------	--

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Maintenance Checklist for AVT Systems

Customer name and place : [CPC Cotentin / Chemin de la Canurie, 50250 La Haye-du-Puits](#)

Contact person at customer / Title : [M. Emmanuel Cornu \(Responsable Maintenance & Travaux neufs\)](#)

Customer Mail & Mobile/Landline : e.cornu-cotentin@cpcpackaging.com / +33 2 33 07 33 11

System SN : [307017](#)

SOB SN : [95203596 – SOB3 JUPITER XP\(X79TO\) 5M DIG CAM 16G V2.9.2.2](#)

Machine Manufacturer/Model/Nickname : [Cerutti / R 980 / Cerutti](#)

Date : [19/01/2023](#)

Name : [Arnaud Darcel](#)


Comments :

Signatures :



Arnaud Darcel 2023-01-19T18:33:43+01:00

BST eltromat FSE



Emmanuel Cornu 2023-01-19T12:03:14+01:00

Customer

On Customer Site

Prior to a Preventive Maintenance :

Check for system affecting modification reports and software releases.

Check for optional light source.

Check with customer about problems, or failure with the system.

1. Cleaning the optical parts :

OK/NOK/NA

- | | |
|---|---|
| - Mirror cleaned with ZEISS lens wipes. | ☒ ☐ ☐ |
| - Camera lens cleaned with ZEISS lens wipes. | ☒ ☐ ☐ |
| - Reflectors cleaned with soft cloth using iso propanol or alcohol. | ☐ ☐ ☒ |
| - Back plate cleaned. | ☒ ☐ ☐ |
| - Computer filter cleaned/replaced | ☐ ☐ ☒ |

2. Camera calibration 100% :

OK/NOK/NA

- | | |
|--|---|
| - Field of View / Period | ☐ ☐ ☒ |
| - Offset/Gain Calibration. | ☐ ☐ ☒ |
| - Zero LED calibration : Anyspeed & Position | ☐ ☐ ☒ |

3. Check functioning of the Lamps :

OK/NOK/NA

- | | |
|---|---|
| - Lamps replacement. : | ☐ ☐ ☒ |
| - Brightness and uniformity of the image checked. | ☒ ☐ ☐ |

4. Replacement of the encoder wheel :

OK/NOK/NA

- | | |
|---|---|
| - Encoder wheel replaced and tightened | ☐ ☐ ☒ |
| - Spring replaced (if necessary) and spring force checked (ca. 1kg/10N) | ☐ ☐ ☒ |

5. Software update :

OK/NOK/NA

- | | |
|-----------------------------------|---|
| - Software Update (if necessary). | ☐ ☒ ☐ |
|-----------------------------------|---|

Old SW version : [2.9.2.2](#)

New SW version : [2.9.2.2](#)

On Customer Site

6. Final check of the running system :

OK/NOK/NA

- Stability of live image checked (without reference image).
- Stripe alignment checked (Normal and reflective mode).
- Registration checked.
- Maximum speed checked.
- Hard drive capacity checked.
- Backup created and saved locally and/or on USB stick.

☒☐☐☐☐☒☒☐☐☒☐☐☒☐☐☒☐☐**7. Backup :**

OK/NOK/NA

- BackupRestore
- Archive Printflow

☒☐☐☒☐☐**Parts replaced during Preventive Maintenance :**

- | | |
|---------------------|-----|
| 1 – Computer Filter | 3 - |
| 2 - | 4 - |

Parts suggested to replace during the next Maintenance :

- | | |
|-----|-----|
| 1 - | 3 - |
| 2 - | 4 - |

Part need to be replaced as soon as possible :

- | | |
|-----|-----|
| 1 - | 3 - |
| 2 - | 4 - |

On Customer Site

Technical datas

Computer name : [COT-CERUTTI](#)

Total Physical Memory : [3.17 GB](#)

Free Space in C Drive (System) : [38 GB](#)

Free Space in D Drive : [394 GB](#)

OS : [Microsoft Windows XP Professional 2002 – SP3](#)

Screen Resolution 1 : [3840x1200](#)

Screen Resolution 1 : [1280x1024](#)

Computer : [95203596 – SOB3 JUPITER XP\(X79TO\) 5M DIG CAM 16G V2.9.2.2](#)

Date : [Sep, 2015](#)

SN : [307017](#)

ACB Firmware : [8/7](#)

Remote Maintenance (Teamviewer)

IP address : [10.50.21.25](#)

Subnet mask : [255.255.255.0](#)

Default gateway : [10.50.21.1](#)

Preferred DNS server : [8.8.8.8](#)

Alternate DNS server :

Teamviewer ID / Version : [996 355 351 / v10](#)

On Customer Site

Notes
