

On Customer Site

Visit Report

Reference :

Commande BSTe France :		Commande BSTe Int. :	
Customer :	Imprimerie Billet	System :	TubeScan DS 430 CP
Customer Contact :	M. Jérôme Nivart	SN :	40.1355
Customer Order number :		Machine Nickname :	RCS

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☒	Under Contract	☒	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☒ Yes				
	☐ No				

		10/01/2023	11/01/2023	12/01/2023	13/01/2023	
Travel To					2	
Start Time			9h00	9h00	10h30	
Lunch Time			1	1	0	
End Time			17h30	18h00	16h30	
Travel From				2.5	2.5	

Details	
---------	--

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Maintenance Checklist for NYQUIST Systems

Available supporting documents :

- Maintenance instruction for Digital Strobe & EagleView systems
- Check list for maintenance

Customer name and place : Imprimerie Billet / 6 route de Romery. 51480 Damery

Contact person at customer : M. Jérôme Nivart

Customer Mail & Mobile/Landline : jerome.nivart@imprimerie-billet.fr / +33 3 26 58 40 11

System Type : EV 430 CP / 318x-0.1944

SN : 40.1355


Machine Manufacturer/Model/Nickname : Press Gallus / EM 280 / RCS

Date : 16/01/2023

Name : Coutellier Vivien

Comments :

Signatures :



BST eltromat FSE

Customer

Prior to a Preventive Maintenance :

On Customer Site

Check for system affecting modification reports and software releases.

Check for optional light source.

Check with customer about problems, or failure with the system.

1. Cleaning the optical parts :

OK/NOK/NA

- Mirror cleaned with lens wipes.
- Camera lens cleaned with lens wipes.
- Reflectors cleaned with soft cloth using iso propanol or alcohol.
- Backing Bar cleaned with soft using iso propanol or alcohol.
- Optionally acryl insert of backing bar replaced.

☒ ☐ ☐
☒ ☐ ☐
☒ ☐ ☐
☒ ☐ ☐
☐ ☒ ☐
2. EagleView – Cleaning and lubricating the rail :

OK/NOK/NA

- Rail cleaned (EagleView only).
- Rail lubricated with silicone oil (EagleView only).
- Length of traverse checked (Calibrate run).

☒ ☐ ☐
☐ ☐ ☒
☐ ☐ ☒
3. Check functioning of the LEDs :

OK/NOK/NA

- LEDs checked.
- Brightness and uniformity of the image checked.

☒ ☐ ☐
☒ ☐ ☐
4. Replacement of the encoder wheel :

OK/NOK/NA

- Encoder wheel replaced and tightened
- Spring replaced (if necessary) and spring force checked (ca. 1kg/10N)

☐ ☒ ☐
☐ ☒ ☐
5. Software update :

OK/NOK/NA

- Software Update (if necessary).

☐ ☒ ☐

Old SW version :

New SW version :

6. Final check of the running system :

OK/NOK/NA

On Customer Site

- | | |
|--|---|
| - Stability of live image checked (without reference image). | ☒ ☐ ☐ |
| - Stripe alignment checked (Normal and reflective mode). | ☒ ☐ ☐ |
| - Registration checked. | ☒ ☐ ☐ |
| - Maximum speed checked. | ☐ ☒ ☐ |
| - Stable location of the EagleView camera checked. | ☒ ☐ ☐ |
| - Hard drive capacity checked. | ☒ ☐ ☐ |
| - Backup created and saved locally and/or on USB stick. | ☒ ☐ ☐ |

7. Backup :

OK/NOK/NA

- | | |
|--------------------------------------|---|
| - NYCAMConfig folder | ☒ ☐ ☐ |
| - NYCAMProg folder | ☒ ☐ ☐ |
| - WindowsImageBackup and/or Image | ☒ ☐ ☐ |
| - Application / Computer Screenshots | ☒ ☐ ☐ |

Parts replaced during Preventive Maintenance :

- | | |
|-----|-----|
| 1 - | 3 - |
| 2 - | 4 - |

Parts suggested to replace during the next Maintenance :

- | | |
|-----|-----|
| 1 - | 3 - |
| 2 - | 4 - |

Part need to be replaced as soon as possible :

- | | |
|-----|-----|
| 1 - | 4 - |
| 2 - | 5 - |

On Customer Site

Technical datas

Computer name : TubeScan 40.1355

Total Physical Memory : 16 GB

Free Space in C Drive (System) : 203 GB

OS : Windows 10 Pro

Screen Resolution Touch : 1024x768

Screen Resolution Full View : 1920x1080

Computer Model : OPTIPLEX 7040

Date : 2019

Remote Maintenance (Teamviewer)

IP address : DHCP Auto

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version :

300 383 299 / v12

On Customer Site

Notes
