

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Atlantique Packaging Cotentin - CPC Cotentin ACU231515 M. Cédric Fautrat Chemin de la Canurie 50250 La Haye-du-Puits France +33 2 33 07 33 11 / +33 7 80 61 36 91 maintenance-cotentin@atlantiquepackaging.com
--	---

Preventive reference number	PMREPORT-272_PM879_2025-05-27
Contract number / Numéro de contrat	CM1912025
Contract date:	2023/01/01 -> 2025/12/31
Machine customer name:	BOBST
Assign to:	DarA
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO045079_WA0020214
Installation date of material:	2018/12/15

TECHNICAL DATAS

PC MODEL	PC-BKA-BSTE02
PC NAME	20214iPQ-Center1-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Enterprise 2016 LTSC
MEMORY RAM	48 GB
FREE SPACE ON C	50.6 / 75.1 GB
FREE SPACE ON D	F:\ 1.71 / 1.81 TB
TEAMVIEWER ID	1 035 997 951 / v15
IP ADDRESS EXTERN FOR INTERNET	IP address : 10.50.21.14 Subnet mask : 255.255.255.0 Default gateway : 10.50.21.1 Preferred DNS server : 10.50.21.1 Alternate DNS server :
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	27/05/2025 08:30
End time PM:	27/05/2025 12:30

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✗	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080 - Duplicate desktop on 1 and 2	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	✗	No need
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommend to exchange every 4 years.
Digitalreplacefilter	✓	Cleaned	Installation date:		2018-12-15
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	✗	v2.17.9 is the maximum software version available
Traversewscamerareplaceflashbulb	✓	8 Flah Bulbs	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	✓	
Traversebackflashflashbulb	✗		Backupimage	✗	Already dpne on this version.
Linecameracleanmirror	✓		Backupsoftware	✓	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Preventive Maintenance - 8 Flash Bulbs replaced

Customer signature:

Name: M. Julien Brisset

Date : 28/05/2025

BST eltromat FRANCE signature:

Name: M. Arnaud Darcel

Date : 28/05/2025


28-May-25 11:18 AM


28-May-25 11:18 AM

ATTACHED PM'S FILE(S)

Offre_PR 250512-0396	RE_BST France - CPC Cotentin (La Haye-du-Puits) - Maintenance Préventive CM1912025 - 1_2 2025	Screenshot 27052025
		