

On Customer Site

Visit Report

Reference :

Commande BSTe France : CM2305054		Call / PM number : PM758	
Customer :	Logre Imprimeurs	System :	Inspection System
Customer Contact :	M. Claude Tina Ndongo	SN :	426902
Customer Order number :	CM2305054 Signé	Machine Nickname :	BOBST M5

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☒	Under Contract	☒	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☐ Yes				
	☒ No				

	09/12/2024					
Travel To	0.5					
Start Time	13h30					
Lunch Time	0					
End Time	15h30					
Travel From	0					

Details	Computer Clean-up Soft and Hard. Archive. Cabling checked. Fans, BIOS... Calibration (FOV,Gain,Offset...).
---------	--

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Maintenance Checklist for NYQUIST Systems

Available supporting documents :

Customer name and place : [Lorge Imprimeurs / 6 Rue Yves Toudic – 69200 – Vénissieux, France](#)

Contact person at customer : [M. Mustafa Ucar \(Responsible Production\)](#)

Customer Mail & Mobile/Landline : mustafa.ucar@lorge.fr / +33 6 82 47 49 59

System Type : [Helios S 430 mm](#)

SN : [426902](#)

Machine Manufacturer/Model/Nickname : [BOBST / M5 430 8K / BOBST](#)

Date : [09/12/2024](#)

Name : [Arnaud Darcel](#)

Comments :

Signatures :



mercredi 11 décembre 2024 11:51:48

BST eltromat FSE



mercredi 11 décembre 2024 11:51:33

Customer

On Customer Site

Prior to a Preventive Maintenance :

Check for system affecting modification reports and software releases.

Check for optional light source.

Check with customer about problems, or failure with the system.

1. Cleaning the optical parts :

OK/NOK/NA

- Mirror cleaned with ZEISS lens wipes. ☒ ☐ ☐
- Camera lens cleaned with ZEISS lens wipes. ☒ ☐ ☐
- Reflectors cleaned with soft cloth using iso propanol or alcohol. ☒ ☐ ☐
- Back plate cleaned. ☒ ☐ ☐
- Computer filter cleaned/replaced ☒ ☒ ☒

2. Camera calibration :

OK/NOK/NA

- Field of View / Period 10.05 : 535.41 mm ☒ ☐ ☐
- Offset/Gain Calibration. ☒ ☐ ☐
- Zero LED calibration : Anyspeed & Position : (Events) ☐ ☐ ☒

3. Check functioning of the Lamps :

OK/NOK/NA

- Lamps replacement. : LED ☐ ☐ ☒
- Brightness and uniformity of the image checked. ☒ ☐ ☐

4. Replacement of the encoder wheel :

OK/NOK/NA

- Encoder wheel replaced and tightened ☒ ☐ ☐
- Spring replaced (if necessary) and spring force checked (ca. 1kg/10N) ☒ ☐ ☐

5. Software update :

OK/NOK/NA

- Software Update (if necessary). ☐ ☒ ☐

Old SW version : 6.0.0.3

New SW version :

On Customer Site

6. Final check of the running system :

OK/NOK/NA

- Stability of live image checked (without reference image).
- Stripe alignment checked (Normal and reflective mode).
- Registration checked.
- Maximum speed checked.
- Hard drive capacity checked.
- Backup created and saved locally and/or on USB stick.

☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐
☐	☒	☐

7. Backup :

OK/NOK/NA

- BackupRestore
- Archive Printflow

☒	☐	☐
☒	☐	☐

Parts replaced during Preventive Maintenance :

- 1 -
- 2 -

Parts suggested to replace during the next Maintenance :

- 1 -
- 2 -

Part need to be replaced as soon as possible :

- 1 -
- 2 -

On Customer Site

Technical datas

Computer name : [AVT-M5](#)

Total Physical Memory : [16 GB](#)

Free Space in C Drive (System) : [194 / 244 GB](#)

Free Space in D Drive : [142 / 221 GB](#)

Free Space in E drive (DOS) :

Free Space in F drive (Backup) : [371 / 931 GB](#)

OS : [Windows Embedded Standard SP1](#)

Screen Resolution Touch : [1920x1080](#)

Computer Model : [W/S HL 1*P2 SOL AIMB-705G2 16 GB WIN7 \(PN25508001\)](#)

ACB Firmware : [49/49](#)

Remote Maintenance (Teamviewer)

IP address : [Automatic IP via MAC 00-0B-AB-E7-4B-9C](#)

Subnet mask :

Default gateway :

Preferred DNS server :


Alternate DNS server :

Teamviewer ID / Version : [1 116 979 919 / v15](#)

On Customer Site

Notes

1- Gain calibration



2- Field of View



On Customer Site

3- Events

