

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	SP Group Soplaril Arras-PLASTIENVASE 231072 M. Mickael Carincotte 1 Rue Claude Bernard 62000 Arras France + 33 3 21 23 68 11 / +33 6 84 64 10 45 mcarincotte@spg-pack.com
--	--

Preventive reference number	PMREPORT-257_PM866_2025-04-11
Contract number / Numéro de contrat	CM1706003
Contract date:	2021/04/01 -> 2024/03/31
Machine customer name:	H12
Assign to:	CouV
Material:	VIDEO_IPQ_Center
Type:	IPQ Center
SN:WA:	ASO025108_WA19450
Installation date of material:	2017/02/15

CUSTOMER ORDER:	2025-0269
-----------------	-----------

TECHNICAL DATAS

PC MODEL	IPC-BG-R7910/BSTE01.0
PC NAME	19450IPQ-CENTER
ADDITIONAL CAMERA INFO	IPQ Center
OPERATION SYSTEM	Windows 7 professionnel
MEMORY RAM	32 GB
FREE SPACE ON C	81.2 GB
FREE SPACE ON D	104 GB
TEAMVIEWER ID	879 943 981 / v15
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	2.17.8
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	10/04/2025 13:30
End time PM:	10/04/2025 17:30

		COMMENTS			COMMENTS
Touchmonitorcalibration	⏸		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	⏸	
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2017-02-15
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	✓		Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓		Softwareipqwsc		.
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		.
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqili		.
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	⏸	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	✓	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	✓	
Led checking+reflector checking+dome	✓	dome legerement craquelé, n'as pas gêné la calibration, a surveiller			
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	✓				

✓: Checked, nothing to report / Vérifié, RAS

✗: Not OK, checked comment / Pas OK, vérifiez commentaires

⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

la matières, la barre de maintient de la matières est tordue.

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:




Name:

Date :


11/04/2025 16:25


11/04/2025 16:25

ATTACHED PM'S FILE(S)

Offre_PR 250409-0374 	2025-0269 	calibration matrix cam 	calibration matrix cam 	calibration matrix cam 
calibration cam 100% 	calibration cam 100% 	calibration cam 100% 	calibration cam 100% 	