

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Wipak 231056 M. Eric Ghesquier Drèce des Bois 59166 Bousbecque France +33 6 07 01 64 56 eric.ghesquier@wipak.com
--	---

Preventive reference number	PMREPORT-370_PM1014_2025-11-18
Contract number / Numéro de contrat	CM2005031
Contract date:	2023/10/01 -> 2026/09/30
Machine customer name:	Flexotecnica
Assign to:	DarA
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO071462 _ WA0021340
Installation date of material:	2020/12/11

TECHNICAL DATAS

PC MODEL	beg-BKA-BST01
PC NAME	21340iPQ-Center1-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Win10Pro
MEMORY RAM	32Go
FREE SPACE ON C	51.6 / 75.7 GB
FREE SPACE ON D	Protocol (F:) 1.62 / 1.81 TB
TEAMVIEWER ID	665 008 695 / v12
IP ADDRESS EXTERN FOR INTERNET	IP Address : 192.168.1.60 Subnet mask : 255.255.255.0 Default gateway : 192.168.1.1 Preferred DNS server : 8.8.8.8 Alternate DNS server : 8.8.4.4
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	17/11/2025 13:15
End time PM:	17/11/2025 17:30

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080 - 24"	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080 - 43"	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✗	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	✓	
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2020-12-11 -> 04 YEAR(S)
Traversecamera	✓		Upscommunicationchecking	✓	Software "euc_win_1_06_022" reinstalled and configured
Traversecameralenscleaning	✓		Softwareupdate	⏸	Last version on this base image
Traversewscamerareplaceflashbulb	⏸	Will be replaced during next maintenance	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓		SoftwareipqWSC		1.9.6
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqili		1.4.3
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	⏸	
TraversewscameracheckzoomirisfocusWSCboard	✓		Softwareremote	✗	No access
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	✓	
Traversebackflashflashbulb	✓		Backupimage	✓	
Linecameracleanmirror	✓		Backupsoftware	✓	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Preventive Maintenance Completed.
- Software "euc_win_1_06_022" reinstalled and configured

Customer signature:

Name: M. David Durand

Date : 18/11/2025

BST eltromat FRANCE signature:

Name: M. Arnaud Darcel

Date : 18/11/2025






18-Nov-25 5:34 PM



18-Nov-25 5:34 PM

ATTACHED PM'S FILE(S)

Picture 17112025 	sysconfig-Setup-Camera-Whitefader-BC 	sysconfig-Setup-Camera-Whitefader-AC 	sysconfig-Setup-Camera-Iris 	sysconfig-Setup-Camera-Zoom 
sysconfig-Setup-LineCam-imp0-PRNU 	sysconfig-Setup-LineCam-imp1-PRNU 	Screenshot 17112025 		