

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Emsur S.p.o 231357 Cyrille Jaguelin / Frédéric Bruant Rue Julienne Robert 53340 Ballée France +33 243 64 36 85 cyrille.jaguelin@emsur.com / frederic.bruant@emsur.com
--	--

Preventive reference number	PMREPORT-341_PM981_2025-10-09
Contract number / Numéro de contrat	CM1709009
Contract date:	2021/01/01 -> 2024/12/31
Machine customer name:	F83
Assign to:	RelR
Material:	VIDEO_IPQ_Center
Type:	iPQ Center / Dual Head Varnish
SN:WA:	ASO056723 _ WA19752
Origin BST France order:	192161
Installation date of material:	2017/07/01

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE01.0-3
PC NAME	19752iPQ-Center1-1
ADDITIONAL CAMERA INFO	iPQ Center / Dual Head Varnish
OPERATION SYSTEM	Windows 10 Entreprise 2016 LTSP
MEMORY RAM	32 GB
FREE SPACE ON C	51.2 - 75.7 GB
FREE SPACE ON D	F:\ 1.71 / 1.81 TB
TEAMVIEWER ID	1 248 594 841 / v15
IP ADDRESS EXTERN FOR INTERNET	IP address : 192.1.1.140 Subnet mask : 255.255.254.0 Default gateway : 192.1.1.252 Preferred DNS server : 192.1.1.5 Alternet DNS server : 192.1.1.1
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	2.17.9

Start time PM:	09/10/2025 09:05
End time PM:	

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓	Ecran view problem d'affichage	Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	⏸	
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2017-07-01 -> 08 YEAR(S)
Traversecamera	✓		Upscommunicationchecking	✓	UPS HS a changer au plus vite
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	✓	Changés	Version upgraded		2.17.9
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	✓		Softwareipqili		1.4.3
Traversewscameracheckcleanmirrorlackercamera	✓		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	⏸	
Traversebackflash	✓		Backupscreenshots	✓	Calibrations
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	✓	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
 ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
 ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name: **Frederic Bruant**
 Date : **09/10/2025**

BST eltromat FRANCE signature:

Name: **Richard Relin**
 Date : **09/10/2025**


 09/10/2025 13:02


 09/10/2025 15:06

ATTACHED PM'S FILE(S)

[Screenshot](#)



[Filtres cam 1](#)



[Filtres cam 100%](#)



[Cam2 filtres](#)

