

On Customer Site

Visit Report

Reference :

Commande BSTe France : CM1912025 / 2		Call / PM number : PM505	
Customer :	CPC Cotentin	System :	Apollo
Customer Contact :	M. Emmanuel Cornu	SN :	307617
Customer Order number :	CM1912025 / 2 signed	Machine Nickname :	Cerutti

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☒	Under Contract	☒	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☐ Yes				
	☒ No				

	27/09/2023					
Travel To	0.5					
Start Time	8h45					
Lunch Time	1					
End Time	12h30					
Travel From	0					

Details	Maintenance Préventive du système d'inspection Apollo sur presse Cerutti. Archivage. Nettoyage des optiques et calibration. Nouveau backup Acronis.
---------	---

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Maintenance Checklist for AVT Systems

Customer name and place : [CPC Cotentin / Chemin de la Canurie, 50250 La Haye-du-Puits](#)

Contact person at customer / Title : [M. Emmanuel Cornu \(Responsable Maintenance & Travaux neufs\)](#)

Customer Mail & Mobile/Landline : e.cornu-cotentin@cpcpackaging.com / +33 2 33 07 33 11

System SN : [307617](#)

SOB SN : [95203644 – SOB3 AR LED P4 FUJITSU 16G WIN7 M.CAM V5.3.1.2](#)

Machine Manufacturer/Model/Nickname : [Cerutti / R 980 / Cerutti](#)

Date : [28/09/2023](#)

Name : [Arnaud Darcel](#)


Comments :

Signatures :



Arnaud Darcel 2023-09-29T10:26:46+02:00

BST eltromat FSE



Emmanuel Cornu 2023-09-29T10:26:30+02:00

Customer

On Customer Site

Prior to a Preventive Maintenance :

Check for system affecting modification reports and software releases.

Check for optional light source.

Check with customer about problems, or failure with the system.

1. Cleaning the optical parts :

OK/NOK/NA

- | | |
|---|---|
| - Mirror cleaned with ZEISS lens wipes. | ☐ ☐ ☒ |
| - Camera lens cleaned with ZEISS lens wipes. | ☒ ☐ ☐ |
| - Reflectors cleaned with soft cloth using iso propanol or alcohol. | ☐ ☐ ☒ |
| - Back plate cleaned. | ☒ ☐ ☐ |
| - Computer filter cleaned/replaced | ☒ ☐ ☐ |

2. Camera calibration :

OK/NOK/NA

Camera 1 :

- | | | |
|--------------------------|-------------------|---|
| - Field of View / Period | 520.12 mm / 10.00 | ☒ ☐ ☐ |
| - Zero LED calibration : | Zero Signal | ☒ ☐ ☐ |

Camera 2 :

- | | | |
|--------------------------|-------------------|---|
| - Field of View / Period | 519.88 mm / 10.00 | ☒ ☐ ☐ |
| - LED calibration : | Zero Signal | ☒ ☐ ☐ |

3. Check functioning of the Lamps :

OK/NOK/NA

- | | |
|---|---|
| - Lamps replacement. : Qty x0 (LED) | ☐ ☐ ☒ |
| - Brightness and uniformity of the image checked. | ☒ ☐ ☐ |

4. Replacement of the encoder wheel :

OK/NOK/NA

- | | |
|---|---|
| - Encoder wheel replaced and tightened | ☐ ☒ ☐ |
| - Spring replaced (if necessary) and spring force checked (ca. 1kg/10N) | ☒ ☐ ☐ |

On Customer Site

5. Software update :

OK/NOK/NA

- Software Update (if necessary).

☐ ☒ ☐

Old SW version : 5.3.1.4

New SW version :

6. Final check of the running system :

OK/NOK/NA

- Stability of live image checked (without reference image).
- Stripe alignment checked (Normal and reflective mode).
- Registration checked.
- Maximum speed checked.
- Hard drive capacity checked.
- Backup created and saved locally and/or on USB stick.

☐ ☐ ☒
☒ ☐ ☐
☐ ☐ ☒
☐ ☐ ☒
☒ ☐ ☐
☒ ☐ ☐

7. Backup :

OK/NOK/NA

- BackupRestore
- Archive Printflow

☒ ☐ ☐
☒ ☐ ☐

Parts replaced during Preventive Maintenance :

1 – Computer Filter 3 -

2 - 4 -

Parts suggested to replace during the next Maintenance :

1 - 3 -

2 - 4 -

Part need to be replaced as soon as possible :

1 - 3 -

2 - 4 -

On Customer Site

Technical datas

Computer name : [COT-CERUTTILCCD](#)

Total Physical Memory : [16 GB](#)

Free Space in C Drive (System) : [26.5 GB](#)

Free Space in D Drive : [303 GB](#)

Free Space in F Drive (Backup) : [276 GB](#)

OS : [Windows 7 Embedded SP1 – v740](#)

Screen Resolution 1 : [1920x1200](#)

Computer : [95203644 – SOB3 AR LED P4 FUJITSU 16G WIN7 M.CAM V5.3.1.2](#)

Date : [Mar, 2016](#)

SN : [307617](#)

ACB Firmware : [33/32](#)

Remote Maintenance (Teamviewer)

IP address : [10.50.21.23](#)

Subnet mask : [255.255.255.0](#)

Default gateway : [10.50.21.1](#)

Preferred DNS server : [8.8.8.8](#)

Alternate DNS server :

Teamviewer ID / Version : [978 044 639 / v15](#)

On Customer Site

Notes
