

On Customer Site

Visit Report

Reference :

Commande BSTe France : CM1911023		Commande BSTe Int. : PM254	
Customer :	Adhex Technologies	System :	TubeScan DS 330 CP
Customer Contact :	M. Franck Leborne	SN :	34.630
Customer Order number :		Machine Nickname :	FS330.01

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☒	Under Contract	☒	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☐ Yes				
	☒ No				

	02/12/2021					
Travel To	0					
Start Time	15h00					
Lunch Time	0					
End Time	16h00					
Travel From	0					

Details	Maintenance Préventive du système TubeScan sur presse Mark Andy XP5000-13A. Mise a jour du software
---------	---

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Maintenance Checklist for NYQUIST Systems

Available supporting documents :

- Maintenance instruction for Digital Strobe & EagleView systems
- Check list for maintenance

Customer name and place : [Adhex Technologies / 44 Rue de Longvic – 21300 - Chenôve](#)

Contact person at customer : [M. Franck Leborne](#)

Customer Mail & Mobile/Landline : f.leborne@adhex.com / +33 6 27 31 68 54

System Type : [DS 330 CP / 318X-0.1388](#)

SN : [34.630](#)

Machine Manufacturer/Model/Nickname : [Mark Andy / XP5000-13A / FS330.01](#)

Date : [02/12/2021](#)


Name : [Richard Relin](#)

Comments :

Signatures :



Richard Relin 2021-12-02T17:47:59+01:00



Franck Leborne 2021-12-02T17:41:56+01:00

BST eltromat FSE

Customer

On Customer Site

Prior to a Preventive Maintenance :

Check for system affecting modification reports and software releases.

Check for optional light source.

Check with customer about problems, or failure with the system.

1. Cleaning the optical parts :

OK/NOK/NA

- Mirror cleaned with ZEISS lens wipes. ☒ ☐ ☐
- Camera lens cleaned with ZEISS lens wipes. ☒ ☐ ☐
- Reflectors cleaned with soft cloth using iso propanol or alcohol. ☒ ☐ ☐
- Backing Bar cleaned with soft using iso propanol or alcohol. ☒ ☐ ☐
- Optionally acryl insert of backing bar replaced. ☐ ☒ ☐

2. EagleView – Cleaning and lubricating the rail :

OK/NOK/NA

- Rail cleaned (EagleView only). ☐ ☐ ☒
- Rail lubricated with silicone oil (EagleView only). ☐ ☐ ☒
- Length of traverse checked (Calibrate run). ☐ ☐ ☒

3. Check functioning of the LEDs :

OK/NOK/NA

- LEDs checked. ☒ ☐ ☐
- Brightness and uniformity of the image checked. ☒ ☐ ☐

4. Replacement of the encoder wheel :

OK/NOK/NA

- Encoder wheel replaced and tightened ☐ ☒ ☐
- Spring replaced (if necessary) and spring force checked (ca. 1kg/10N) ☐ ☒ ☐

5. Software update :

OK/NOK/NA

- Software Update (if necessary). ☒ ☐ ☐

Old SW version : [7.0.52.96](#)

New SW version : [7.2.67.100](#)

On Customer Site

6. Final check of the running system :

OK/NOK/NA

- Stability of live image checked (without reference image).
- Stripe alignment checked (Normal and reflective mode).
- Registration checked.
- Maximum speed checked.
- Stable location of the EagleView camera checked.
- Hard drive capacity checked.
- Backup created and saved locally and/or on USB stick.

☒	☐	☐
☒	☐	☐
☒	☐	☐
☐	☒	☐
☐	☐	☒
☒	☐	☐
☒	☐	☐

7. Backup :

OK/NOK/NA

- NYCAMConfig folder
- NYCAMProg folder
- WindowsImageBackup and/or Image
- Application / Computer Screenshots

☒	☐	☐
☒	☐	☐
☒	☐	☐
☒	☐	☐

Parts replaced during Preventive Maintenance :

1 -	3 -
2 -	4 -

Parts suggested to replace during the next Maintenance :

1 – Backplate(voir notes)	3 -
2 –	4 -

Part need to be replaced as soon as possible :

1 -	4 -
2 -	5 -

On Customer Site

Technical datas

Computer name : [TubeScan-PC](#)

Total Physical Memory : [8 GB](#)

Free Space in C Drive (System) : [417 GB](#)

OS : [Win10](#)

Screen Resolution Touch : [1024x768](#)

Screen Resolution Full View : [1920x1080](#)

Computer Model : [DELL D11S001](#)

Date : [2017](#)

Remote Maintenance (Teamviewer)

IP address : [DHCP Auto](#)

Subnet mask :

Default gateway :

Preferred DNS server :

Alternate DNS server :

Teamviewer ID / Version : [747 900 731 / v12](#)

On Customer Site

Notes

