

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elxis.group/	ADAPA SCHUR FLEXIBLES Uni Packaging AVERDOINGT 231784 Aurélien Gervois Hameau de Neuville Planque 62127 Averdoint France +33 6 02 03 59 57 aurelien.gervois@schurflexibles.com
--	---

Preventive reference number	PMREPORT-138_PM722_2024-10-17
Contract number / Numéro de contrat	CM2103037
Contract date:	2021/07/01 -> 2024/08/31
Machine customer name:	ROTO10
Assign to:	CouV
Material:	VIDEO_IPQ_Center
Type:	iPQ Center / Dual Head Varnish
SN:WA:	ASO053692_WA0020579
Installation date of material:	2019/03/31

CUSTOMER ORDER:	CDE CLIENT BPA du 16102024
-----------------	----------------------------

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE01.0-3
PC NAME	Please fill system information
ADDITIONAL CAMERA INFO	iPQ Center / Dual Head Varnish
OPERATION SYSTEM	Please fill system information
MEMORY RAM	Please fill system information
FREE SPACE ON C	Please fill system information
FREE SPACE ON D	
TEAMVIEWER ID	1 169 554 447 / v12
IP ADDRESS EXTERN FOR INTERNET	10.40.141.5
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	II	
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2019-03-31
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	II	
Traversewscamerareplaceflashbulb	✓		Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.11
Camerachangefiltercheckfan	✓		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		-
Traversewscameracheckflashbulblackerflash	II		Softwareipqll		1.4.3
Traversewscameracheckcleanmirrorlackercamera	II		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswsoboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	II		Operatorinstructions	II	
Traversebackflash	II		Backupscreenshots	✓	
Traversebackflashflashbulb	II		Backupimage	II	
Linecameracleanmirror	✓	Rayures sur la vitre de la cam 2 provoquant une ligne rouge a l'ecran, la calibration n'a pas solutionné le probleme, besoin de remplacer le miroir	Backupsoftware	II	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalallignementtoprint	II				
Camera white calibration	✓	White and black calibration on 2 cameras			

- ✓: Checked, nothing to report / Vérifié, RAS
 X: Not OK, checked comment / Pas OK, vérifiez commentaires
 II: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:


Name: Aurélien Gervais

Date: 17/10/2024

BST eltromat FRANCE signature:

Name: C.V

Date: 14/10/2024



A. Gervais



ATTACHED PM'S FILE(S)

<u>Offre PR 241011-0211</u>	<u>CDE CLIENT BPA du 16102024</u>	<u>SH2410-0293</u>	<u>BL2410-0228</u>	<u>AR CDE 241016-0219</u>
				
<u>camera1-calibration</u>	<u>camera1-black calibration</u>	<u>camera2-before calibration</u>	<u>camera2-after calibration</u>	
				

A. Germeis



17/10/2024