

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	MCC NANTES SIMEDIT sautron ACU304137 M. William Breit ZA de, Tournebride RD65 44880 Sautron France +33 2 28 07 24 00 william.breit@mcclabel.com
--	--

Preventive reference number	PMREPORT-197_PM794_2025-01-31
Contract number / Numéro de contrat	CM1911024
Contract date:	2022/01/01 -> 2023/12/31
Machine customer name:	8S
Assign to:	CouV
Material:	VIDEO_IPQ_Check_eco
Type:	iPQ Check Eco
SN:WA:	WA19084
Installation date of material:	2020/01/24

TECHNICAL DATAS

PC MODEL	PrecisionT3610
PC NAME	12345IPQ-Center
ADDITIONAL CAMERA INFO	iPQ Check Eco
OPERATION SYSTEM	Windows7
MEMORY RAM	16Go
FREE SPACE ON C	27.6Go
FREE SPACE ON D	99.1Go
TEAMVIEWER ID	1 630 203 396 / v12
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	2.2.1
UPG OR DNG VERSION DURING MAINTENANCE	2.6.3

Start time PM:	28/01/2025 15:30
End time PM:	28/01/2025 17:30

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920X1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview			Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	⏸	
Digitalcheckfan	✓		Upsdatebatteryexchanged		2023/01/24
Digitalreplacefilter	✓		Installation date:		2020-01-24 -> 02 YEAR(S)
Linecameracleanmirror	✓		Upscommunicationchecking	⏸	
Led checking+reflector checking+dome	✗		Softwareupdate	✓	
Linecameramechanicalcheck	✓		Version upgraded		2.6.3
Linecamerabacklightmechanicalcheckjigs	✓		Softwareipqtu		1.8.5
Cameramechanicalalignementtoprint	✓		Softwareipqili		1.4.2
Camerawhitecalibration	✓		Softwareworkflowcommunication	⏸	
			Softwareremote	⏸	
			Operatorinstructions	⏸	
			Backupscreenshots	✓	
			Backupimage	✓	
			Backupsoftware	✓	

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Front light a remplacer

Remplacement des câbles video a prevoir

Il faudrait prØvoir de clim pour le pupitre et remplacer le boitier du PC pour integrer une clim

Le recepteur video de l'Øcran tactile chauffe, il faudrait le remplacer

Prevoir un dØplacement des coffret PC et armoire electrique au sol

Customer signature:


Name: **M. Mathieu Cabelauer**

Date :

BST eltromat FRANCE signature:

Name: **Coutellier Vivien**

Date :


31/01/2025 16:24


31/01/2025 16:24