

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	CCL - Moussy-le-Neuf --- M. Luc Carmaran 1 rue Font des Bries 77230 Moussy-le-Neuf France +33 6 33 82 45 70 lcarmaran@cclind.com
--	---

Preventive reference number	PMREPORT-366_PM1010_2025-11-13
Contract number / Numéro de contrat	CM2511085
Contract date:	2025/11/01 -> 2028/10/31
Machine customer name:	342
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 330 4K / M2089aC 0.0833
SN:WA:	ASO107429_50.3029
Origin BST France order:	242198
Installation date of material:	2024/09/03

TECHNICAL DATAS

PC MODEL	OptiPlex 3090 / Tag C8JRG24
PC NAME	Tubescan503029
ADDITIONAL CAMERA INFO	TubeScan DS 330 4K / M2089aC 0.0833
OPERATION SYSTEM	Windows 11 Pro / 23H2
MEMORY RAM	32 GB
FREE SPACE ON C	120 / 235 GB
FREE SPACE ON D	-
TEAMVIEWER ID	513 338 086 / v15
IP ADDRESS EXTERN FOR INTERNET	Automatic IP
ORIGINAL VERSION	8.0.30.29481
UPGRADE OR DOWNGRADE VERSION LAST INTERVENTION	8.0.36.31792 from E2343
UPG OR DNG VERSION DURING MAINTENANCE	8.0.42.40103.hotfix-14

Start time PM:	13/11/2025 08:15
End time PM:	13/11/2025 11:00

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1920x1080 - 21.5"	Encoder wheel status	✓	
View monitor resolution		1920x1080 - 22"	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	✓	
PC's fans ?	✓		Date UPS's batteries exchanged ?		OLD UPS APC NEW UPS EATON recommand to exchange every 5 years.
PC's filter	II		Installation date:		2024-09-03 -> 01 YEAR(S)
Lens cleaning	✓	1 camera looking up	UPS communication?	✓	
Mirror cleaning	✓		Softwareworkflowcommunication	II	
Backing or RRB cleaining	✓	DS430 model	Check Teamviewer access	✓	ID 513 338 086 / v15
Lens Focal	✓		Calibration of camera detail & 100%camera	II	
Camera alignement with printing	✓		Operators instruction ?	II	
Check web under camera	✓		Screenshots	✓	On v8.0.42.40103.hotfix-14
Height compensator calib	✓		ACRONIS ?	✓	On v8.0.42.40103.hotfix-14
Encoder offset calib	✓		Backup application	✓	On v8.0.42.40103.hotfix-14
Only with EV- LED calibrations	II				

Kisspoint only with 2 cameras



Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- ✓ ENCODER WHEEL:: 2RDHO234275
- ✓ LED Board equipped V40 L=140mm: 1ELLT256485
- ✓ LED Board equipped V40 L=160mm: 1ELLT256486
- ✓ ENCODER'S SPRING
- ✓ BACKPLATE W/B

- ✓: Checked, nothing to report / Vérifié, RAS
- ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
- ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance Completed.
- Software upgrade to the latest released version.
- UV LED must be replaced during next maintenance.
- Fonctional system.

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :

13-Nov-25 11:01 AM

13-Nov-25 10:43 AM

ATTACHED PM'S FILE(S)

Picture 13112025	Screenshot 13112025
	