

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	CCL Package Label - Pharma (Chilly-Mazarin) ACU231910 M. Jean-Charles Campana 20 Avenue Arago 91380 Chilly-Mazarin France +33 7 63 04 72 66 jccampana@cclind.com
--	---

Preventive reference number	PMREPORT-286_PM910_2025-06-05
Contract number / Numéro de contrat	CM1708005
Contract date:	2022/01/01 -> 2024/12/31
Machine customer name:	Digicon 330
Assign to:	NguJ
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 330 4000 /M2032ac/0.0833
SN:WA:	ASO091757_50.2387
Installation date of material:	2023/04/06

TECHNICAL DATAS

PC MODEL	7090
PC NAME	TUBESCAN502387
ADDITIONAL CAMERA INFO	TubeScan DS 330 4000 /M2032ac/0.0833
OPERATION SYSTEM	Windows 10 pro
MEMORY RAM	16 gb
FREE SPACE ON C	170 gb
FREE SPACE ON D	
TEAMVIEWER ID	1 172 145 443
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	7.4.44.111
UPG OR DNG VERSION DURING MAINTENANCE	7.4.67.34209

Start time PM:	05/06/2025 14:30
End time PM:	05/06/2025 15:00

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✓	
View monitor resolution		1920x1080	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✗				
PC's fans ?	⏸				
PC's filter	⏸		Installation date:		2023-04-06
Lens cleaning	✓				
Mirror cleaning	✓		Software workflow communication	⏸	
Backing or RRB cleaning	✓		Check Teamviewer access	✗	NO INTERNET CONNECTION
Lens Focal	✓		Calibration of camera detail & 100% camera	⏸	
Camera alignment with printing	✓		Operators instruction ?	⏸	
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	⏸	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	⏸				
Kisspoint only with 2 cameras	⏸				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- | | |
|--------------------------|---|
| ☐ | ENCODER WHEEL:: 2RDHO234275 |
| ☐ | LED Board equipped V40 L=140mm: 1ELLT256485 |
| ☐ | LED Board equipped V40 L=160mm: 1ELLT256486 |
| ☐ | ENCODER'S SPRING |
| ☐ | BACKPLATE W/B |

- : Checked, nothing to report / Vérifié, RAS
: Not OK, checked comment / Pas OK, vérifiez commentaires
: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

image a un phénomène de stretching, l'image se déforme.
cela peut etre du au codeur un peu loin de la camera.
il faudrait replacer le codeur a un autre endroit

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :



05/06/2025 16:12