

On Customer Site

Visit Report

Reference :

Commande BSTe France : SERV220615DT		Call / PM number : E1215	
Customer :	CCL Package Label	System :	TubeScan DS 430 4K
Customer Contact :	M. Aymeric Beaumont	SN :	42.1896/ASO078965
Customer Order number :	SERV220615DT	Machine Nickname :	S21

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☒	Under Warranty	☐	Out of Warranty	☒
Instruction	☐ Yes				
	☒ No				

	17 / 06 /2022					
Travel To	2.0					
Start Time	9h00					
Lunch Time	0					
End Time	11h00					
Travel From	2.0					

Details	Troubleshooting : White cable plugged straight into PLC with AVT workflow cable. Solution: Rewinder control was not checked.
---------	--

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Maintenance Checklist for NYQUIST Systems

Available supporting documents :

- Maintenance instruction for Digital Strobe & EagleView systems
- Check list for maintenance

Customer name and place : [CCL Package Label / 20 Avenue Arago – 91380 – Chilly-Mazarin - France](#)

Contact person at customer : [M. Aymeric Beaumont\(Responsable de Maintenance\)](#)

Customer Mail & Mobile/Landline : abeaumont@cclind.com/06 66 06 87 61

System Type : [TubeScan DS 430 4K / M2032C-0.1111](#)

SN : [42.1896](#)


Machine Manufacturer/Model/Nickname : [Rotocontrol/ S21](#)

Date : [17/06/2022](#)


Name : [Richard Relin](#)

Comments :

Signatures :



Richard Relin 2022-06-17T11:01:29+02:00



Aymeric Beaumont 2022-06-17T11:01:14+02:00

BST eltromat FSE

Customer

On Customer Site

Notes
