

On Customer Site

Visit Report

Reference :

Commande BSTe France : BPA232186		Intervention. : E1695	
Customer :	ETILABEL	System :	PS5000
Customer Contact :	ALAIN GATI	SN / WA :	ASO098744
Customer Order number :		Machine Nickname :	M4

Visit Purpose :

Mechanical Preparation	☐	Installation	☒	Start-up	☒
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☐	Under Warranty	☐	Out of Warranty	☐
Instruction	☒ Yes				
	☐ No				

	17/07/2023					
Travel To	2					
Start Time	10h00					
Lunch Time	1					
End Time	16h15					
Travel From	2					

Details	INSTALLATION camera PS5000 SUR LA M5 Le guide bande de la M4 se bloque et passe en mode manuel lors de fortes chaleurs (EKR ProKey30) TEKNEK SUR M5 LE 24V n'arrive pas au matériel (relais semble défectueux) PS3000 sur M1 moteur continu 12V semble défectueux.
---------	--

Purpose of the visit completed : Yes ☒ No ☐

Need a new visit : Yes ☐ No ☒

On Customer Site

Customer name and place : [Etilabel](#)

Contact person at customer : [M. Alain Gati](#)

Customer Mail & Mobile/Landline :

System Type : [PS5000](#)

WA/ASO :


Machine Manufacturer/Model/Nickname : [MARKANDY](#)

Date : [17/07/2023](#)


Name : [Coutellier Vivien](#)

Comments :

Signatures :



BST eltromat FSE



Customer