

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Livcer M. Charles de Livonnière 593 avenue Blaise Pascal - Lotissement Anaconda 2 77550 Moissy Cramayel France charles.livonniere@livcer.com
---	--

Ticket number:	E2212
Customer order:	
Machine customer name:	S820
Origin BST France order:	222010A
AR:	
Tiket type:	INTERVENTION
Assign to:	RelR -> richard.relin@bst.group
Ticket date:	2024/09/05
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 850 4000 / X104iC-0.2222
SN:WA:	ASO085184_44.2248
Installation date of material:	2022/07/04
Teamviewer:	637 410 545 / v15
PC model:	OptiPlex 7090
Original Application Version	7.4.59.21261
Upgraded VERSION application during intervention	7.4.64.29287 from Ticket E2212
Upgraded VERSION application during last intervention	E7.4.64.29287 from Ticket E2212

3 day(s) of intervention calculation

2024 / 2024	Tue.26/11	Wed.27/11	Thu.28/11
Drive time	1.5		
AM Start	08:30		
AM End			
PM Start			
PM End			16:30
Drive time			

Start date of intervention	2024/11/26-08:30
End date of intervention	2024/11/28-16:30
Reason:	Qlink Edidor + QLink Press/Rewinder Instruction
Actions:	- Upgrade to v7.4.644.29287. - I/O control using "Vison" mode works only on "unwinder" mode. I/O cable rewired from extended terminal block to PLC1. - Test "Slow Down" & "Stop" ok on "Unwinder" & "slitting" mode.
Solution:	slow down and stop are working in all modes.
Remarks:	
Ticket status:	open

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name:

Date :


28/11/2024 15:14

BS

T

eltromat FRANCE signature:

Name:

Date :


28/11/2024 15:15