

Englisch

Customer: AMCOR Flexibles Packaging France SAS Boulevard de la République 453 39196 Froges	Nr. ACU231963	place of installation: AMCOR Flexibles Packaging France SAS Boulevard de la République 453 39196 Froges	purchaser: purchase no.: telephone: contact person: technician:	Fabien Orgiassa 4530940443 Jacky Guilbaud Thiele, Armin	comm. BST: comm. customer: machine: service order: Internal	WA 0021484 / ASO075451 ASR010250 0
---	----------------------	--	--	--	--	--

BST equipment: regi_star 20
additions/ comments:

driven distance	plate	fellow passenger
— km	—	



day	date	travel time		break h	working time		break h	travel time		break h	comment	total	working time				travelling time			
		from	to		from	to		from	to				N	50	100		N	50	100	
Mon	03.11.2025	6:30	18:30	0,75							much traffic in france	11,25					8,00	3,25		
Tue	04.11.2025				8:00	18:00	0,75					9,25	8,00	1,25						
Wed	05.11.2025				8:00	18:00	0,75					9,25	8,00	1,25						
Thu	06.11.2025				8:00	18:30	0,75					9,75	8,00	1,75						
Fri	07.11.2025																			
Sat	08.11.2025																			
Sun	09.11.2025																			
Mon	10.11.2025																			
Tue	11.11.2025																			
Wed	12.11.2025																			
Thu	13.11.2025																			
Fri	14.11.2025																			
Sat	15.11.2025																			
Sun	16.11.2025																			
short report												Σ	39,50	24,00	4,25		8,00	3,25		

Commisioning of a regi_star 20 at a 6 colour gravure print machine (SAM)
The system was already installed before together with an iPQ-Check Pro by SAM few years ago, the power was switched on

Tuesday: Checkup of the signals beetween the system and the machine together with Jürg Spillmann (INDUR)
Wednesday: Troubleshooting because problems with motor signals of side register, short test print without register
Thursday: Test print with 4 colours (PU 2-5), first setup of the system together with Jürg Spillmann, short operator training

Result: It was possible to controll, but there are many issues and problems to get a stable web run inside the machine, in this condition it is not possible to keep the register.satisfactory.

☐ Material required as per attached list! ☐ work completed ☒ additional visit necessary

39196 Froges 06.11.2025	signature technician 	signature customer 
	Thiele, Armin	Jacky Guilbaud



Customer survey