

BST eltromat France SARL

Impasse de la Noisette – CE 402
F-91374 Verrières le Buisson cedex
bstfrance@bstfrance.net

+33 169 200741
+33 169 207808

Sarl au capital de € 207630
RC Corbeil B91645 – NAF : 4652 Z

Siret : 329 210 322 000 15
NIF : FR 64 329 210 322

Relations bancaires

BNP PARIBAS Verrières le Buisson

Agence 01326

Cpte 2701563733

BIC : BNPA FR PP MAS

IBAN : FR76 3000 4013 2600 0270 1563 733

RAPPORT DE REPARATION

CLIENT/CUSTOMER: JABOULEY

TYPE DE MATERIEL/MATERIEL : EKR1500C302-01 – Nr. 1458IP54

NOM MACHINE: -

CALL : E853

DATE : 16/07/2021

PERSONNE EN CHARGE : JB NGUYEN

INFORMATION CLIENT SUR LA PANNE / CUSTOMER INFORMATION ON BREAKDOWN :


-

DATE	16/07/2021
TEMPS/TIME	1H
Total	1H

EKR1500

Call **E853** of **JABOULEY** on **EKR1500C302-01 (EKR1500C302-01). SN/ASO: 1458 IP54**

customer	JABOULEY
system name	EKR1500C302-01
Reference	E853
CallType	REPAIR
Datecall	16/07/2021 15:17
Reason	CUSTOMER DRILLED THE BOARD - NEED TO REPLACE A RESISTANCE
Datevisite	16/07/2021 15:17
Remark	
Createdat	16/07/2021 15:18
Updatedat	
STATUT	solved



TEST AVEC EMS1 + SENSOR IR2005 - > OK