

Englisch

Customer:	Nr.	place of installation:	purchaser:	0	comm. BST:	WA Bulhosas		
			purchase no.:	0	comm. customer:			
Av. Primeiro de Maio, 3700-227			telephone:		machine:			
Porto, Portugal			contact person:	José Moreira	service order:	0		
			technician:	Fernández Santiago	Internal	0		
BST equipment:					driven distance		plate	fellow passenger
TubeScan								
<i>additions/ comments:</i>					km			

day	date	travel time		break h	working time		break h	travel time		break h	comment	total	working time				travelling time					
		from	to		from	to		from	to				N	50	100		N	50	100			
Mon	23/09/2024				10:15	10:45						0,50	0,50									
short report											Σ	0,50	0,50									

Connection with TubeScan Sn. 50.2395.

The folder NYCAMReports was a Direct Access to their Server. The access was not working.

His informatic made again the redirection of the folder and now all is working correctly.

☐ Material required as per attached list!

☒ work completed☐ additional visit necessary

0 26/09/2024	signature technician _____ Fernández Santiago	signature customer _____
--------------	--	--------------------------