

On Customer Site

Visit Report

Reference :

Commande BSTe France :		Call / PM number : E1693	
Customer :	MCC (Sautron)	System :	
Customer Contact :	M. Wiliam Breit	ASO / WA :	
Customer Order number :		Machine Nickname :	9NGV

Visit Purpose :

Mechanical Preparation	☐	Installation	☐	Start-up	☐
Maintenance	☐	Under Contract	☐	Out of Contract	☐
Troubleshoot	☒	Under Warranty	☐	Out of Warranty	☒
Instruction	☐ Yes				
	☒ No				

	29 / 06 / 2023		/ /	/ /	/ /	/ /
Travel To	0					
Start Time	05h30					
Lunch Time	0					
End Time	11h00					
Travel From	0					

Details	Troubleshoot 9NGV ; Branchement en direct DELL a Beckhoff. Manque de communication entre Beckhoff et Dell.
---------	--

Purpose of the visit completed :

Yes ☒

No ☐

Need a new visit :

Yes ☐

No ☒

On Customer Site

Customer name and place : [MCC / Zi de Tournebride, R.D. 65 F, 44880 Sautron](#)

Contact person at customer / Title : [M. William Breit \(Responsable de production\)](#)

Customer Mail & Mobile/Landline : william.breit@mcclabel.com / +33 2 28 07 24 00

System Type : [iPQ Check /WVstar](#)

Date : [29/06/2023](#)

Name : [Relin Richard](#)

Comments :

Signatures :



Richard Relin 2023-06-30T11:41:21+02:00



Julien GUELLAEN g 2023-06-30T11:39:03+02:00

BST eltromat FSE

Customer

On Customer Site

Notes

- Bien éteindre le PC apartir de l'application.
- Faire offre pour onduleur pour système IPQ 9NGV
- Faire offre pour cables illi RJ45 7S