

Englisch

Customer:	Nr.	place of installation:	purchaser:	comm. BST:	ASO088518
CIF TANGER		Compagnie Industrielle des Fibres Douar Hjar Nh	purchase no.:	comm. customer:	
Compagnie Industrielle des Fibres Dou		Commune de Boukhalef Tanger	telephone:	machine:	Comexi F2 MP
Commune de Boukhalef Tanger		Tanger 90025	contact person:	service order:	
Tanger 90025		Morocco	technician:	Internal	0

BST equipment:

iPQ - Check

additions/ comments:

driven distance		plate	fellow passenger
90	km	6927MPZ	

day	date	travel time		break h	working time		break h	travel time		break h	comment	total	working time				travelling time				
		from	to		from	to		from	to				N	50	100		N	50	100		
Tue	10/06/2025	5:30	12:30		12:30	18:00	0,50					12,00	1,00	4,00			7,00				
Wed	11/06/2025	8:00	8:30		8:30	10:00						2,00	1,50				0,50				
short report											Σ	14,00	2,50	4,00			7,50				

short report

Motivo de visita: Reemplazo de objetivo y placa de control.

Se desmonto la camara, se hizo una limpieza integral, se reemplazo el objetivo SpaceCom y la placa de control. Se volvio a configurar la camara.

El equipo queda funcionando correctamente.

Reason for visit: Replacement of lens and control plate.

Disassembled the camera, did a complete cleaning, replaced the SpaceCom lens and control board. Re-configured the camera. □

The equipment is now operating correctly.

☐ Material required as per attached list!

☒ work completed

☐ additional visit necessary

Morocco 11/06/2025	signature technician	 Sainz, Agustin 11/06/2025 10:55	signature customer	 BOUHMAÏ Houssein 11/06/2025 10:54
--------------------	----------------------	--	--------------------	---



Customer survey