

Englisch

Customer: SOMA spol. s.r.o. Dukelských hrdinů 1199 56301 Lanskrout Czech Republic	Nr. ACU256004	place of installation: Flexoprint (1980) Ltd. 12 Hashenhav Str. 448200 Barkan Industrial Zone Israel	purchaser: purchase no.: telephone: contact person: technician:	0 0 Avi Saad Relin, Richard	comm. BST: comm. customer: machine: service order: Internal	WA 0023347 / ASO108962 m/c 020/73 ASR009996 0
--	----------------------	---	--	--------------------------------------	--	--

BST equipment: *register* *vision* *automation* *offset* *web guide*

additions/ comments:

driven distance	plate	fellow passenger
600	km	GV-202-

day	date	travel time		break h	working time		break h	travel time		break h	comment	total	working time				travelling time				
		from	to		from	to		from	to				N	50	100		N	50	100		
Sun	14/09/2025	3:30	14:00									10.50							10.50		
Mon	15/09/2025	8:00	10:00		10:00	17:00	1.00	17:00	18:00			9.00	6.00				2.00	1.00			
Tue	16/09/2025	7:00	8:30		8:30	16:00	1.00	16:00	17:00			9.00	6.50				1.50	1.00			
Wed	17/09/2025	7:00	8:30		8:30	18:00	1.00	18:00	20:00			12.00	6.50	2.00			1.50	2.00			
Thu	18/09/2025	7:00	8:30		8:30	16:00	1.00	16:00	17:00			9.00	6.50				1.50	1.00			
Fri	19/09/2025	15:00	23:30									8.50					8.00	0.50			
Sat	20/09/2025																				
Sun	21/09/2025																				
Mon	22/09/2025																				
Tue	23/09/2025																				
Wed	24/09/2025																				
Thu	25/09/2025																				
Fri	26/09/2025																				
Sat	27/09/2025																				
short report												Σ	58.00	25.50	2.00			14.50	5.50	10.50	

As mentioned in Acceptance all is in place and working.

Only PDF Plate Auditor has not been tested with a correct picture lack of file formats being correct from preprese.

And i recommend to install AC on new cabinet like older system.

☐ Material required as per attached list! ☒ work completed ☐ additional visit necessary

Israel 18/09/2025

signature technician 18/09/2025 16:11

Relin, Richard

signature customer 18/09/2025 16:11



Customer survey