

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Simpack 30 Rue Saint-Antoine de Rochefort 72400 La Ferté-Bernard FRANCE
---	---

Ticket number:	E2750
Customer order:	BPA DU 14102025
Machine customer name:	D600
Origin BST France order:	222470
AR:	
Tiket type:	SERVICE_INSTRUCTION
Assign to:	NguJ -> jean-baptiste.nguyen@bst.group
Ticket date:	2025/10/22
Material:	WEB_GUIDING
Type:	EKR CON600 CLS CAM 100 EMS21-100-2.5-20X5-C
SN:WA:	ASO09456
Installation date of material:	2025/10/22
Teamviewer:	
PC model:	
Original Application Version	

1 day(s) of intervention calculation

2025 / 2025	Wed.22/10
Drive time	2
AM Start	08:30
AM End	13:00
PM Start	13:30
PM End	16:30
Drive time	2.5

Start date of intervention	2025/10/22-08:30
End date of intervention	2025/10/22-16:30
Reason:	INSTRUCTIONS AUX OPERATEURS SUR CLS CAM 100 + EKR CON600
Actions:	CALIBRATION PLATE LOST BY CUSTOMER NEED TO SEND NEW ONE TO MAKE CALIBRATION
Solution:	
Remarks:	
Ticket status:	solved
Service instructions (only in case of Service instructions/ Intervention/ Installation ticket)	BEAUCHESNE FERRA ROSELYNE LAINE CASSANDRA LUCAS JAYSON DENIAU AMANDINE DEROUIN REBECCA RICHARD

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :


22/10/2025 16:12

BS

T

eltromat FRANCE signature:

Name:

Date :


22/10/2025 16:07

ATTACHED CALL'S FILE(S)

[BPA DU 14102025](#)

