

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elaxis.group/	DCM Usimeca ACU231017 M. Thomas Vayer 45 avenue Guillaeraies 92000 Nanterre France +33 7 72 39 56 27 thomas.vayer@dcm.fr
---	--

Ticket number:	E2725
Customer order:	BPA du 24092025
Machine customer name:	31397_SOUTH AFRICA
Origin BST France order:	252110
AR:	
Tiket type:	INTERVENTION
Assign to:	NguJ -> jean-baptiste.nguyen@bst.group
Ticket date:	2025/09/29
Material:	VIDEO_IPQ_Center
Type:	DCM31397
SN:WA:	ASO114035_WA0023691
Installation date of material:	2025/09/23
Teamviewer:	502 339 168
PC model:	
Original Application Version	

4 day(s) of intervention calculation

2025 / 2025	Tue.30/09	Wed.01/10	Thu.02/10	Fri.03/10
Drive time	0.5			0.5
AM Start	09:00			09:00
AM End				
PM Start				
PM End				12:47
Drive time	0.5			0.5

Start date of intervention	2025/09/30-09:00
End date of intervention	2025/10/03-12:47
Reason:	set waste indicator on ipq
Actions:	test at 50m/min - 100m/min and at deceleration ejectors system eject 2 before and 2 after defects
Solution:	
Remarks:	
Ticket status:	solved

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :



03/10/2025 12:33

BST eltromat FRANCE signature:

Name:

Date :



03/10/2025 12:34

ATTACHED CALL'S FILE(S)

BPA du 24092025	waste indicator settings
	