

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	CONSTANTIA Jeanne d'Arc SAS 231032 M. François Bodhuin B.P. 51 52300 Vecqueville France +33 3 25 94 77 75 / +33 6 74 57 25 31 francois.bodhuin@cflex.com
--	---

Preventive reference number	PMREPORT-78_PM639_2024-05-03
Contract number / Numéro de contrat	CM2104038
Contract date:	2022/01/01 -> 2024/12/31
Machine customer name:	Comexi
Assign to:	DarA
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO077271_WA21553
Installation date of material:	2022/02/24

CUSTOMER ORDER:	Offre_PR 240429-0113 - BPA
-----------------	----------------------------

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE03.0-3
PC NAME	21553iPQ-Center1-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Enterprise LTSC
MEMORY RAM	64.0 GB
FREE SPACE ON C	37.2/75.1 GB
FREE SPACE ON D	F:\ 0.831 / 894 GB
TEAMVIEWER ID	1 126 221 355 / v15
IP ADDRESS EXTERN FOR INTERNET	IP Address : 10.140.164.140 Subnet mask : 255.255.255.0 Default gateway : 10.140.164.254 Preferred DNS server : 8.8.8.8 Alternate DNS server : 8.8.4.4
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

	COMMENTS		COMMENTS
Touchmonitorcalibration	OK	Ipqchecksynchronization	OK
Pscreenresolutiontouch	1920x1080	Ipqencoderwheelfixing	OK
Pscreenresolutionview	1920x1080	Ipqencoderwheelstatus	OK
Hardwareconditionscrews	OK	Ipqencoderwheelrunningonweb	OK
Hardwareconditioncables	OK	Alarmstatusindicator	OK
Hardwareconditionconnectors	OK	Upsbatteryexchanged	KO
Digitalcheckfan	OK	Upsdatebatteryexchanged	UPS builder recommend to exchange every 4 years.
Digitalreplacefilter	OK	Installation date:	2022-02-24
Traversecamera	OK	Upscommunicationchecking	OK
Traversecameralenscleaning	OK	Softwareupdate	KO Need v3.x for next maintenance (Defect History rotation)
Traversewscamerareplaceflashbulb	OK 8 Flash Bulbs (Offre_PR 240429-0113)	Version upgraded	
Traversewscameracleanwindows	OK	Softwareipqtcu	1.12
Camerachangefiltercheckfan	OK	SoftwareipqWSC	1.9.6
Traversewscamerashadowreducingbackplate	OK	Softwareipqpps	2.2
Traversewscameracheckflashbulblackerflash	NA	Softwareipqili	1.4.3
Traversewscameracheckcleanmirrorlackercamera	NA	Softwareworkflowcommunication	NA
TraversewscameracheckzoomirisfocusWSCboard	OK	Softwareremote	OK Need manual cable plugging
Traversewscameracalibrationzoomirisfocus	OK	Operatorinstructions	OK
Traversebackflash	NA	Backupscreenshots	OK
Traversebackflashflashbulb	NA	Backupimage	KO
Linecameracleanmirror	OK	Backupsoftware	OK
Led checking+reflector checking+dome	OK		
Linecameramechanicalcheck	OK		

Linecamerabacklightmechanicalcheckjigs	OK	
Camera mechanical alignementtoprint	OK	Magenta to Yellow
Camera white calibration	OK	

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name:

Date :


Franck Gavier 2024-05-03T11:53:45+02:00

BS

T eltromat FRANCE signature:

Name:

Date :


Arnaud Darcel 2024-05-03T11:54:01+02:00

ATTACHED PM'S FILE(S)

Offre_PR 240429-0113 	Offre_PR 240429-0113 - BPA 	Chronopost 	UPS 	sysconfig-Setup-Camera-Whitefader 
sysconfig-Setup-Camera-Iris 	sysconfig-Setup-Camera-Zoom 	sysconfig-Setup-LineCam0-Alignment 	sysconfig-Setup-LineCam0-PRNU 	sysconfig-Setup-LineCam1-Alignment 
sysconfig-Setup-LineCam1-PRNU 	Kiss Point 			