

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	CPC Cotentin 231515 M. Cédric Fautrat Chemin de la Canurie 50250 La Haye-du-Puits France +33 2 33 07 33 11 / +33 7 80 61 36 91 maintenance-cotentin@cpcpackaging.com
--	---

Preventive reference number	PMREPORT-61_PM614_2024-04-04
Contract number / Numéro de contrat	CM1912025
Contract date:	2023/01/01 -> 2025/12/31
Machine customer name:	BOBST
Assign to:	DarA
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO045079_WA0020214
Installation date of material:	2018/12/15

CUSTOMER ORDER:	CDE CLIENT BPA du 2503204
-----------------	---------------------------

TECHNICAL DATAS

PC MODEL	PC-BKA-BSTE02
PC NAME	20214iPQ-Center1-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Enterprise 2016 LTSB
MEMORY RAM	48 GB
FREE SPACE ON C	50.7 / 75.1 GB
FREE SPACE ON D	F:\ 1.76 / 1.81 TB
TEAMVIEWER ID	1 035 997 951 / v15
IP ADDRESS EXTERN FOR INTERNET	IP address : 10.50.21.14 Subnet mask : 255.255.255.0 Default gateway : 10.50.21.1 Preferred DNS server : 10.50.21.1 Alternate DNS server :
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

	COMMENTS		COMMENTS
Touchmonitorcalibration	OK	Ipqchecksynchronization	OK
Pscreenresolutiontouch	1920x1080	Ipqencoderwheelfixing	OK
Pscreenresolutionview	1920x1080	Ipqencoderwheelstatus	OK
Hardwareconditionscrews	OK	Ipqencoderwheelrunningonweb	OK
Hardwareconditioncables	OK	Alarmstatusindicator	OK
Hardwareconditionconnectors	OK	Upsbatteryexchanged	KO
Digitalcheckfan	OK	Upsdatebatteryexchanged	UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	NA	Installation date:	2018-12-15
Traversecamera	OK	Upscommunicationchecking	OK
Traversecameralenscleaning	OK	Softwareupdate	NA
Traversewscamerareplaceflashbulb	OK	Version upgraded	
Traversewscameracleanwindows	OK	Softwareipqtcu	1.12
Camerachangefiltercheckfan	OK	Softwareipqwsc	1.9.6
Traversewscamerashadowreducingbackplate	OK	Softwareipqpps	2.2
Traversewscameracheckflashbulblackerflash	NA	Softwareipqili	1.4.3
Traversewscameracheckcleanmirrorlackercamera	NA	Softwareworkflowcommunication	OK
Traversewscameracheckzoomirisfocuswscboard	OK	Softwareremote	OK
Traversewscameracalibrationzoomirisfocus	OK	Operatorinstructions	NA
Traversebackflash	NA	Backupscreenshots	OK
Traversebackflashflashbulb	NA	Backupimage	KO
Linecameracleanmirror	OK	Backupsoftware	OK
Led checking+reflector checking+dome	OK		ipq-center_bak_2024_03_26_17_18_35
Linecameramechanicalcheck	OK		
Linecamerabacklightmechanicalcheckjigs	OK		
Camera mechanical alignment to print	OK		

Camera white calibration

OK

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name: **tautrat cedric**

Date : **05/04/2024**



BS

BS

T

el

tro

mat

FRANCE signature:

Name:

Date :



Arnaud Darcel 2024-04-05T09:31:28+02:00