

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	SP Group Soplaril Arras-PLASTIENVASE 231072 M. Mickael Carincotte 1 Rue Claude Bernard 62000 Arras France + 33 3 21 23 68 11 / +33 6 84 64 10 45 mcarincotte@spg-pack.com
--	--

Preventive reference number	PMREPORT-64 PM620 2024-04-12
Contract number / Numéro de contrat	CM1706003
Contract date:	2021/04/01 -> 2024/03/31
Machine customer name:	H11
Assign to:	CouV
Material:	VIDEO_IPQ_Check_eco
Type:	IPQ Check Eco
SN_VA:	ASO040662_WA20041
Installation date of material:	2022/02/14

TECHNICAL DATAS

PC MODEL	Please fill system information
PC NAME	Please fill system information
ADDITIONAL CAMERA INFO	IPQ Check Eco
OPERATION SYSTEM	Please fill system information
MEMORY RAM	Please fill system information
FREE SPACE ON C	Please fill system information
FREE SPACE ON D	
TEAMVIEWER ID	1 030 573 402 / v15
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	2.17.8
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

	COMMENTS		COMMENTS
Touchmonitorcalibration	OK	Ipqchecksynchronization	OK
Pscreenresolutiontouch	1920x1080	Ipqencoderwheelfixing	OK
Pscreenresolutionview		Ipqencoderwheelstatus	OK
Hardwareconditionscrews	OK	Ipqencoderwheelrunningonweb	OK
Hardwareconditioncables	OK	Alarmstatusindicator	OK
Hardwareconditionconnectors	OK	Upsbatteryexchanged	NA
Digitalcheckfan	OK	Upsdatebatteryexchanged	UPS builder recommend to exchange every 4 years.
Digitalreplacefilter	OK	Installation date:	2022-02-14
Linecameracleanmirror	OK	Upscommunicationchecking	OK
Led checking+reflector checking+dome	OK	Softwareupdate	NA
Linecameramechanicalcheck	OK	Version upgraded	
Linecamerabacklightmechanicalcheckjigs	OK	Softwareipqtcu	
Cameraamechanicalalignmenttoprint	NA	Softwareipqli	
Camerawhitecalibration	NA	Softwareworkflowcommunication	NA
		Softwareremote	KO
		Operatorinstructions	NA
		Backupscreenshots	OK
		Backupimage	NA
		Backupsoftware	OK

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- En mécanique causant tremblement du support cam
conigé en changeant roulean et pulier AVOIR si servient dans
le futur
- Supression des jobs (démarrage Penk)

Customer signature:

Name: Flank

Date: 12/04/24

BST eltromat FRANCE signature:

Name: Conte Pher

Date: 12/04/24




100 Claude Bernard - CS 20073
62002 ARRAS Cedex - France
Tel. 03 21 23 68 11



BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	SP Group Soplaril Arras-PLASTIENVASE 231072 M. Mickael Carincotte 1 Rue Claude Bernard 62000 Arras France + 33 3 21 23 68 11 / +33 6 84 64 10 45 mcarincotte@spg-pack.com
--	--

Preventive reference number	PMREPORT-63_PM619_2024-04-12
Contract number / Numéro de contrat	CM1706003
Contract date:	2021/04/01 -> 2024/03/31
Machine customer name:	H12
Assign to:	CouV
Material:	VIDEO_IPQ_Center
Type:	IPQ Center
SN:WA:	ASO025108 _ WA19450
Installation date of material:	2017/02/15

CUSTOMER ORDER:	CDE CLIENT: 24A29855
-----------------	----------------------

TECHNICAL DATAS

PC MODEL	IPC-BG-R7910/BSTE01.0
PC NAME	Please fill system information
ADDITIONAL CAMERA INFO	IPQ Center
OPERATION SYSTEM	Please fill system information
MEMORY RAM	Please fill system information
FREE SPACE ON C	Please fill system information
FREE SPACE ON D	
TEAMVIEWER ID	879 943 981 / v15
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	2.17.8
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

	COMMENTS		COMMENTS
Touchmonitorcalibration	OK	Ipqchecksynchronization	OK
Pcscreenresolutiontouch	1920x1080	Ipqencoderwheelfixing	OK
Pcscreenresolutionview	1920x1080	Ipqencoderwheelstatus	OK
Hardwareconditionscrews	OK	Ipqencoderwheelrunningonweb	OK
Hardwareconditioncables	OK	Alarmstatusindicator	OK
Hardwareconditionconnectors	OK	Upsbatteryexchanged	NA
Digitalcheckfan	OK	Upsdatebatteryexchanged	UPS builder recommend to exchange every 4 years.
Digitalreplacefilter	OK	Installation date:	2017-02-15
Traversecamera	OK	Upscommunicationchecking	OK
Traversecameralenscleaning	OK	Softwareupdate	NA
Traversewscamerareplaceflashbulb	OK	Version upgraded	
Traversewscameracleanwindows	OK	Softwareipqtou	
Camerachangefiltercheckfan	OK	Softwareipqwsc	
Traversewscamerashadowreducingbackplate	OK	Softwareipqpps	
Traversewscameracheckflashbulblackerflash	OK	Softwareipqli	
Traversewscameracheckcleanmirrorlackercamera	OK	Softwareworkflowcommunication	NA
Traversewscameracheckzoomirisfocuswscboard	OK	Softwareremote	KO
Traversewscameracalibrationzoomirisfocus	NA	Operatorinstructions	NA
Traversebackflash	NA	Backupscreenshots	OK
Traversebackflashflashbulb	NA	Backupimage	NA
Linecameracleanmirror	OK	Backupsoftware	OK
Led checking+ reflector checking+dome	OK		
Linecameramechanicalcheck	OK		
Linecamerabacklightmechanicalcheckjigs	OK		
Camera mechanical alignment top print	NA		

Camera white calibration

NA

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- Remplacement disque protocol par SSD
- Preventif
- Test Onduleur OK

Customer signature:

Name:

F. Bont

Date:

BST eltromat FRANCE signature:

Name:

Corbelle

Date:

12/04/2024

