

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	SBE Societe bretonne étiquette ACU531001 M. Nicolas Robert 17 Rue Théodore Botrel 35550 Pipriac France + 33 2 99 34 37 49 atelier.flexo@sbe-etiquettes.fr
--	--

Preventive reference number	PMREPORT-147_PM719_2024-11-07
Contract number / Numéro de contrat	CM2310056
Contract date:	2023/10/01 -> 2026/09/30
Machine customer name:	MPS 6
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 330 4K / BF3-M2-0.0833
SN:WA:	ASO042900_38.1105
Installation date of material:	2021/09/27

TECHNICAL DATAS

PC MODEL	OptiPlex 5060
PC NAME	38-1105-Tubescan4K
ADDITIONAL CAMERA INFO	TubeScan DS 330 4K / BF3-M2-0.0833
OPERATION SYSTEM	Windows 10 Pro / 2018
MEMORY RAM	16 GB
FREE SPACE ON C	180 / 237 GB
FREE SPACE ON D	-
TEAMVIEWER ID	1 201 626 730 / v12
IP ADDRESS EXTERN FOR INTERNET	IP address : 192.168.88.192 Subnet mask : 255.255.255.0 Default gateway : 192.168.88.75 Preferred DNS server : 192.168.88.75 Alternate DNS server : 192.168.210.93
ORIGINAL VERSION	7.2.81.120
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

		COMMENTS			COMMENTS
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✓	
View monitor resolution		1600x900	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	Released
Cables status ?	✓		Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	✗	
PC's fans ?	✓		Date UPS's batteries exchanged ?		2022/01/01
PC's filter	⏸		Installation date:		2021-09-27 -> 02 YEAR(S)
Lens cleaning	✓		UPS communication?	✓	
Mirror cleaning	✓		Software workflow communication	✓	Mapping on PDF Folder created with IT.
Backing or RRB cleaning	✓		Check Teamviewer access	✓	Teamviewer upgrade & Anydesk
Lens Focal	✓		Calibration of camera detail & 100% camera	✓	
Camera alignment with printing	✓		Operators instruction ?	✓	PDF Comparison
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	⏸	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	⏸				
Kisspoint only with 2 cameras	⏸				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

	ENCODER WHEEL:: 2RDHO234275
	LED Board equipped V40 L=140mm: 1ELLT256485
	LED Board equipped V40 L=160mm: 1ELLT256486
	ENCODER'S SPRING
	BACKPLATE W/B

- : Checked, nothing to report / Vérifié, RAS
: Not OK, checked comment / Pas OK, vérifiez commentaires
: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Maintenance preventive sur presse MPS. Configuration réseau pour mapping sur dossier PDF.
Explication du fonctionnement du PDF Comparison.

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :


jeudi 7 novembre 2024 17:28:29


jeudi 7 novembre 2024 17:28:03

ATTACHED PM'S FILE(S)

Picture 07112024	Screenshot 07112024
	