

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	CCL Package Label - Pharma (Chilly-Mazarin) ACU231910 M. Jean-Charles Campana 20 Avenue Arago 91380 Chilly-Mazarin France +33 7 63 04 72 66 jccampana@cclind.com
--	---

Preventive reference number	PMREPORT-285_PM909_2025-06-05
Contract number / Numéro de contrat	CM1708005
Contract date:	2022/01/01 -> 2024/12/31
Machine customer name:	SH351
Assign to:	NguJ
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 330 4K / 0.0833
SN:WA:	ASO101365_50.2762
Installation date of material:	2024/03/01

TECHNICAL DATAS

PC MODEL	OptiPlex 7090
PC NAME	TUBESCAN502762
ADDITIONAL CAMERA INFO	TubeScan DS 330 4K / 0.0833
OPERATION SYSTEM	Windows 10 Pro Version 21H1 (OS Build 19043.1766)
MEMORY RAM	16 GB(2x 8 3200 MHz)
FREE SPACE ON C	Please fill system information
FREE SPACE ON D	
TEAMVIEWER ID	1316828566
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	7.4.57.20297
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	05/06/2025 14:11
End time PM:	

		COMMENTS			COMMENTS
Touch monitor calibration	II	view monitor is missing	Fixation encoder	✓	
Touch monitor resolution		1920x1080	Encoder wheel status	✓	
View monitor resolution		1920x1080	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	uncheck iso 24V-GND to use alarmset it must have y cable to have placement queue control + alarm set
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	II	
PC's fans ?	II		Date UPS's batteries exchanged ?		OLD UPS APC NEW UPS EATON recommend to exchange every 5 years.
PC's filter	II		Installation date:		2024-03-01 -> 01 YEAR(S)
Lens cleaning	✓		UPS communication?	✓	
Mirror cleaning	✓		Softwareworkflowcommunication	II	
Backing or RRB cleaining	✓		Check Teamviewer access	✗	
Lens Focal	✓		Calibration of camera detail & 100%camera	II	
Camera alignement with printing	II	impossible to check, machine is not running	Operators instruction ?	II	
Check web under camera	II	impossible to check, machine is not running	Screenshots	✓	
Height compensator calib	II		ACRONIS ?	II	
Encoder offset calib	II		Backup application	II	
Only with EV- LED calibrations	II				
Kisspoint only with 2 cameras	II				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- | | |
|--------------------------|---|
| ☐ | ENCODER WHEEL:: 2RDHO234275 |
| ☐ | LED Board equipped V40 L=140mm: 1ELLT256485 |
| ☐ | LED Board equipped V40 L=160mm: 1ELLT256486 |
| ☐ | ENCODER'S SPRING |
| ☐ | BACKPLATE W/B |

- ☒: Checked, nothing to report / Vérifié, RAS
☒: Not OK, checked comment / Pas OK, vérifiez commentaires
☐: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :


05/06/2025 15:51


05/06/2025 15:53

ATTACHED PM'S FILE(S)

[screenshots](#)



[photos](#)

