

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Adhex Technologies 231128 M. Franck Leborne 44 Rue de Longvic 21300 Chenôve France +33 6 21 31 68 54 f.leborne@adhex.com
--	---

Preventive reference number	PMREPORT-219_PM822_2025-02-18
Contract number / Numéro de contrat	CM1911023
Contract date:	2023/01/01 -> 2025/12/31
Machine customer name:	M2200
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 250 4K / M2089aC0.0833
SN:WA:	ASO083905_42.2111
Origin BST France order:	212586
Installation date of material:	2022/03/21

TECHNICAL DATAS

PC MODEL	OptiPlex 7090 / Tag 3Y420L3
PC NAME	TubeScan422111
ADDITIONAL CAMERA INFO	TubeScan DS 250 4K / M2089aC0.0833
OPERATION SYSTEM	Windows 10 Pro / v21H1
MEMORY RAM	16 GB
FREE SPACE ON C	124 / 237 GB
FREE SPACE ON D	-
TEAMVIEWER ID	917 121 279 / v15
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	7.4.48.116
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	18/02/2025 10:30
End time PM:	18/02/2025 12:30

COMMENTS			COMMENTS		
Touch monitor calibration	✓	Software Screen positions changed	Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✓	
View monitor resolution		1920x1080	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓	Some new attachment to release the tension on the connectors. GND cable from press connected to OH.	Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	✗	
PC's fans ?	⏸		Date UPS's batteries exchanged ?		2022/03/01
PC's filter	⏸		Installation date:		2022-03-21 -> 02 YEAR(S)
Lens cleaning	✓	Looking up	UPS communication?	✓	Smart UPS SMT750IC Software reinstalled
Mirror cleaning	✓		Softwareworkflowcommunication	✓	QLink
Backing or RRB cleaining	✓	Slightly dirty	Check Teamviewer access	✓	
Lens Focal	✓		Calibration of camera detail & 100%camera	⏸	
Camera alignement with printing	✓		Operators instruction ?	⏸	
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	⏸	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	⏸				

Kisspoint only with 2 cameras



Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- ✓ ENCODER WHEEL:: 2RDHO234275
- ✓ LED Board equipped V40 L=140mm: 1ELLT256485
- ✓ LED Board equipped V40 L=160mm: 1ELLT256486
- ✓ ENCODER'S SPRING
- ✓ BACKPLATE W/B

- ✓: Checked, nothing to report / Vérifié, RAS
- ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
- ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance Done. UPS Software reinstalled

Customer signature:

Name:

Date :



mardi 18 février 2025 11:59:23

BST eltromat FRANCE signature:

Name:

Date :



mardi 18 février 2025 11:59:43

ATTACHED PM'S FILE(S)

Picture 18022025	Screenshot 18022025
	