

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	CPC Cotentin 231515 M. Cédric Fautrat Chemin de la Canurie 50250 La Haye-du-Puits France +33 2 33 07 33 11 / +33 7 80 61 36 91 maintenance-cotentin@cpckpackaging.com
--	--

Preventive reference number	PMREPORT-62_PM618_2024-04-04
Contract number / Numéro de contrat	CM1912025
Contract date:	2023/01/01 -> 2025/12/31
Machine customer name:	Rotomec
Assign to:	DarA
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO059410_WA0020827
Installation date of material:	2018/12/05

TECHNICAL DATAS

PC MODEL	IPC-BKA-BSTE02
PC NAME	20827iPQ-Center1-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Enterprise 2016 LTSC
MEMORY RAM	48 GB
FREE SPACE ON C	50.2 / 75.1 GB
FREE SPACE ON D	F:\ 1.54 / 1.81 TB
TEAMVIEWER ID	1 296 881 336 / v15
IP ADDRESS EXTERN FOR INTERNET	IP address : 10.50.21.13 Subnet mask : 255.255.255.0 Default gateway : 10.50.21.1 Preferred DNS server : 10.50.21.1 Alternate DNS server :
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

		COMMENTS			COMMENTS
Touchmonitorcalibration	OK		Ipqchecksynchronization	OK	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	OK	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	OK	
Hardwareconditionscrews	OK		Ipqencoderwheelrunningonweb	OK	
Hardwareconditioncables	OK		Alarmstatusindicator	OK	
Hardwareconditionconnectors	KO		Upsbatteryexchanged	NA	
Digitalcheckfan	NA		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	NA		Installation date:		2018-12-05 -> 05 YEAR(S)
Traversecamera	OK		Upscommunicationchecking	OK	
Traversecameralenscleaning	OK		Softwareupdate	NA	
Traversewscamerareplaceflashbulb	OK	8 Flash Bulbs	Version upgraded		
Traversewscameracleanwindows	OK		Softwareipqtcu		1.12
Camerachangefiltercheckfan	OK		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	NA		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	NA		Softwareipqli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	NA		Softwareworkflowcommunication	OK	
Traversewscameracheckzoomirisfocuswsboard	OK		Softwareremote	OK	1 296 881 336 / v15
Traversewscameracalibrationzoomirisfocus	OK		Operatorinstructions	NA	
Traversebackflash	OK		Backupscreenshots	OK	
Traversebackflashflashbulb	KO	Not replaced	Backupimage	NA	
Linecameracleanmirror	OK		Backupsoftware	OK	ipq-center_bak_2024_03_26_15_29_00
Led checking+reflector checking+dome	OK				
Linecameramechanicalcheck	OK				
Linecamerabacklightmechanicalcheckjigs	OK				
Cameramechanicalalignementtoprint	OK				

OK Vertical line reported --> fixed

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :



BST eltromat FRANCE signature:

Name:

Date :



Arnaud Darcel 2024-04-05T09:31:55+02:00