

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	ADAPA SCHUR FLEXIBLES Uni Packaging AVERDOINGT 231784 Aurélien Gervois Hameau de Neuville Planque 62127 Averdoingt France +33 6 02 03 59 57 aurelien.gervois@adapa-group.com
--	---

Preventive reference number	PMREPORT-343_PM985_2025-10-14
Contract number / Numéro de contrat	CM2103037
Contract date:	2021/09/01 -> 2027/08/31
Machine customer name:	ROTO10
Assign to:	RelR
Material:	VIDEO_IPQ_Center
Type:	iPQ Center / Dual Head Varnish
SN:WA:	ASO053692_WA0020579
Installation date of material:	2019/03/31

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE01.0-3
PC NAME	20579-IPQ-1
ADDITIONAL CAMERA INFO	iPQ Center / Dual Head Varnish
OPERATION SYSTEM	Win10Pro
MEMORY RAM	64GO
FREE SPACE ON C	Please fill system information
FREE SPACE ON D	
TEAMVIEWER ID	1 169 554 447 / v12
IP ADDRESS EXTERN FOR INTERNET	10.40.141.5
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	14/10/2025 12:49
End time PM:	

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓	Remise dans l'ordre des écrans	Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	⏸	Semble être en fin de vie. A changer.
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2019-03-31
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	✓	1 seul sur Cam 1. Les flashs sont neuves apart sa donc pas de changement de toutes	Version upgraded		
Traversewscameracleanwindows	⏸		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓		Softwareipqwsc		1.9.7
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		-
Traversewscameracheckflashbulblackerflash	✓		Softwareipqli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	✓		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	⏸	
Traversebackflash	✓		Backupscreenshots	✓	Calibrations
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	✓	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Cameramechanicalalignementtoprint	✓				
Camera whitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name: **Aurelien Gervois**

Date : **15/10/2025**

BST eltromat FRANCE signature:

Name: **Richard Relin**

Date : **15/10/2025**


15/10/2025 11:51


15/10/2025 11:51

ATTACHED PM'S FILE(S)

Cam 1 filtros	Filtres cam 2	Filtres 100%	Screenshots calibration
			