

|                                                                                                                                                                                                                                              |                                                                                                                                                                                              |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>BST Eltromat France SARL</b><br>Impasse de la Noisette - CE402<br>F-91374 Verrières le Buisson<br>Tél.: +33 1 69 20 07 41<br>Email: bstfrance@bst.group<br>Web: <a href="https://www.bst.elaxis.group/">https://www.bst.elaxis.group/</a> | <b>CCL Package Label - Tabacco (Chilly-Mazarin)</b><br>ACU231910<br>Mme Nina Bühlmann<br>3 rue Denis Papin<br>91380<br>Chilly-Mazarin<br>France<br>+33 6 63 75 08 72<br>nbuhlmann@cclind.com |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

|                                     |                               |
|-------------------------------------|-------------------------------|
| Preventive reference number         | PMREPORT-354_PM997_2025-11-04 |
| Contract number / Numéro de contrat | CM1708005                     |
| Contract date:                      | 2022/01/01 -> 2024/12/31      |
| Machine customer name:              | R02R                          |
| Assign to:                          | DarA                          |
| Material:                           | VIDEO_Tubescan_DS             |
| Type:                               | DS 250 HR1 / M2051dC 0.1111   |
| SN:WA:                              | ASO097804_50.2619             |
| Installation date of material:      | 2023/12/31                    |

TECHNICAL DATAS

|                                                |                                                    |
|------------------------------------------------|----------------------------------------------------|
| PC MODEL                                       | OptiPlex 3090 / Tag 2DYL6S3                        |
| PC NAME                                        | TubeScan502619                                     |
| ADDITIONAL CAMERA INFO                         | DS 250 HR1 / M2051dC 0.1111                        |
| OPERATION SYSTEM                               | Windows 11 Pro / 23H2                              |
| MEMORY RAM                                     | 16 GB                                              |
| FREE SPACE ON C                                | 103 / 235 GB                                       |
| FREE SPACE ON D                                | bst_qlink\$ (lblchisrv43.ccleurope.cclind.net) (Q) |
| TEAMVIEWER ID                                  | 1 949 451 254 / v15                                |
| IP ADDRESS EXTERN FOR INTERNET                 | Automatic IP                                       |
| ORIGINAL VERSION                               | 7.4.60.22448                                       |
| UPGRADE OR DOWNGRADE VERSION LAST INTERVENTION | TubeScan_8.0.42.38312.hotfix-10 from E2689         |
| UPG OR DNG VERSION DURING MAINTENANCE          | 8.0.42.38312.hotfix-14                             |

|                |                  |
|----------------|------------------|
| Start time PM: | 04/11/2025 13:30 |
| End time PM:   | 04/11/2025 16:00 |

| COMMENTS                         |   |                             | COMMENTS                                  |   |                                                                                                            |
|----------------------------------|---|-----------------------------|-------------------------------------------|---|------------------------------------------------------------------------------------------------------------|
| Touch monitor calibration        | ✓ |                             | Fixation encoder                          | ⏸ |                                                                                                            |
| Touch monitor resolution         |   | 1024x768                    | Encoder wheel status                      | ⏸ |                                                                                                            |
| View monitor resolution          |   | 1920x1080                   | Encoder wheel on web?                     | ⏸ |                                                                                                            |
| Fixation screws of system?       | ✓ |                             | Spring(s) encoder status ?                | ⏸ |                                                                                                            |
| Cables status ?                  | ✓ |                             | Alarm indicator status ?                  | ⏸ |                                                                                                            |
| Connectors cameras (well tight?) | ✓ |                             | UPS battery exchanged ?                   | ⏸ |                                                                                                            |
| PC's fans ?                      | ✓ |                             | Date UPS's batteries exchanged ?          |   | <a href="#">OLD UPS APC NEW UPS EATON</a> recommand to exchange every 5 years.                             |
| PC's filter                      | ⏸ |                             | Installation date:                        |   | 2023-12-31 -> 01 YEAR(S)                                                                                   |
| Lens cleaning                    | ✓ | 1 camera looking down       | UPS communication?                        | ✓ | UPS software, shutdown settings, and task scheduling configured with customer's UPS (Eaton 5SC750 & 3S700) |
| Mirror cleaning                  | ⏸ |                             | Softwareworkflowcommunication             | ✗ | bst_qlink\$ (lblchisrv43.ccleurope.cclind.net) (Q)                                                         |
| Backing or RRB cleaining         | ✓ |                             | Check Teamviewer access                   | ✓ | 1 949 451 254 / v15                                                                                        |
| Lens Focal                       | ✓ |                             | Calibration of camera detail & 100%camera | ⏸ |                                                                                                            |
| Camera alignement with printing  | ✓ |                             | Operators instruction ?                   | ⏸ |                                                                                                            |
| Check web under camera           | ✗ | The web is moving up & down | Screenshots                               | ✓ | On v8.0.42.38312.hotfix-14                                                                                 |
| Height compensator calib         | ✓ |                             | ACRONIS ?                                 | ✓ | On v8.0.42.38312.hotfix-14                                                                                 |
| Encoder offset calib             | ✓ |                             | Backup application                        | ✓ | On v8.0.42.38312.hotfix-14                                                                                 |
| Only with EV- LED calibrations   | ⏸ |                             |                                           |   |                                                                                                            |

Kisspoint only with 2 cameras



Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- ✓  ENCODER WHEEL:: 2RDHO234275
- ✓  LED Board equipped V40 L=140mm: 1ELLT256485
- ✓  LED Board equipped V40 L=160mm: 1ELLT256486
- ✓  ENCODER'S SPRING
- ✓  BACKPLATE W/B

- ✓: Checked, nothing to report / Vérifié, RAS
- ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
- ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance Completed - Software upgraded to the latest release version. - UPS software, shutdown settings, and task scheduling configured with customer ' s UPS (Eaton 5SC750 & 3S700).

Customer signature:

Name:

Date :

  
04-Nov-25 3:24 PM

BST eltromat FRANCE signature:

Name:

Date :

  
04-Nov-25 3:22 PM

**ATTACHED PM'S FILE(S)**

|                                                                                   |                                                                                   |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| <a href="#">Picture 04112025</a>                                                  | <a href="#">Screenshot 04112025</a>                                               |
|  |  |