

|                                                                                                                                                                                                                                              |                                                                                                                                                                              |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>BST Eltromat France SARL</b><br>Impasse de la Noisette - CE402<br>F-91374 Verrières le Buisson<br>Tél.: +33 1 69 20 07 41<br>Email: bstfrance@bst.group<br>Web: <a href="https://www.bst.elexis.group/">https://www.bst.elexis.group/</a> | <b>BBC CELLPACK Packaging</b><br>ACU231328<br>M. Laurent Keller<br>20 Rue Bumkirch - BP20<br>68720<br>Illfurth<br>France<br>+33 3 89 68 79 73<br>laurent.keller@cellpack.com |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

|                                     |                               |
|-------------------------------------|-------------------------------|
| Preventive reference number         | PMREPORT-248_PM858_2025-04-02 |
| Contract number / Numéro de contrat | CM2309055                     |
| Contract date:                      | 2023/10/01 -> 2026/09/30      |
| Machine customer name:              | i71                           |
| Assign to:                          | DarA                          |
| Material:                           | VIDEO_IPQ_Center              |
| Type:                               | iPQ View R/V                  |
| SN:WA:                              | ASO101171_WA0022815           |
| Origin BST France order:            | 232317                        |
| Installation date of material:      | 2024/02/12                    |

TECHNICAL DATAS

|                                       |                                   |
|---------------------------------------|-----------------------------------|
| PC MODEL                              | beg-BKA-BSTE05                    |
| PC NAME                               | 22815-IPQ-1                       |
| ADDITIONAL CAMERA INFO                | iPQ View R/V                      |
| OPERATION SYSTEM                      | Windows 10 Enterprise LTSC / 2018 |
| MEMORY RAM                            | 16 GB                             |
| FREE SPACE ON C                       | 70.8 / 99.9 GB                    |
| FREE SPACE ON D                       | F: 392 / 394 GB                   |
| TEAMVIEWER ID                         | 1 378 156 515 / v15               |
| IP ADDRESS EXTERN FOR INTERNET        | DHCP Automatic                    |
| ORIGINAL VERSION                      | 3.1.1                             |
| UPG OR DNG VERSION DURING MAINTENANCE | No software upgrade recommended   |

|                |                  |
|----------------|------------------|
| Start time PM: | 02/04/2025 13:30 |
| End time PM:   | 01/04/2025 18:00 |

|                                              |   | COMMENTS                                             |                               |   | COMMENTS                                                                         |
|----------------------------------------------|---|------------------------------------------------------|-------------------------------|---|----------------------------------------------------------------------------------|
| Touchmonitorcalibration                      | ✓ |                                                      | Ipqchecksynchronization       | ⏸ |                                                                                  |
| Pcscreenresolutiontouch                      |   | 1920x1080 - 24" (Touch)                              | Ipqencoderwheelfixing         | ⏸ |                                                                                  |
| Pcscreenresolutionview                       |   | 1920x1080 - 43" (View)                               | Ipqencoderwheelstatus         | ⏸ |                                                                                  |
| Hardwareconditionscrews                      | ⏸ |                                                      | Ipqencoderwheelrunningonweb   | ⏸ |                                                                                  |
| Hardwareconditioncables                      | ✓ |                                                      | Alarmstatusindicator          | ⏸ |                                                                                  |
| Hardwareconditionconnectors                  | ✓ |                                                      | Upsbatteryexchanged           | ✗ |                                                                                  |
| Digitalcheckfan                              | ✓ |                                                      | Upsdatebatteryexchanged       |   | <a href="#">UPS builder</a> recommand <a href="#">to exchange</a> every 4 years. |
| Digitalreplacefilter                         | ✓ |                                                      | Installation date:            |   | 2024-02-12 -> 01 YEAR(S)                                                         |
| Traversecamera                               | ✓ |                                                      | Upscommunicationchecking      | ✓ |                                                                                  |
| Traversecameralenscleaning                   | ✓ |                                                      | Softwareupdate                | ✗ | Last version on this Base Image                                                  |
| Traversewscamerareplaceflashbulb             | ✗ | 8 Flash Bulbs to replace during the next maintenance | Version upgraded              |   |                                                                                  |
| Traversewscameracleanwindows                 | ✓ |                                                      | Softwareipqtcu                |   | 1.13                                                                             |
| Camerachangefiltercheckfan                   | ✓ |                                                      | Softwareipqwsc                |   | 1.9.7                                                                            |
| Traversewscamerashadowreducingbackplate      | ✓ |                                                      | Softwareipqpps                |   | 2.2                                                                              |
| Traversewscameracheckflashbulblackerflash    | ✗ | Flash Bulbs to replace during the next maintenance   | Softwareipqili                |   | -                                                                                |
| Traversewscameracheckcleanmirrorlackercamera | ✓ |                                                      | Softwareworkflowcommunication | ⏸ |                                                                                  |
| Traversewscameracheckzoomirisfocuswsboard    | ✓ |                                                      | Softwareremote                | ✓ |                                                                                  |
| Traversewscameracalibrationzoomirisfocus     | ✓ |                                                      | Operatorinstructions          | ✗ |                                                                                  |
| Traversebackflash                            | ⏸ |                                                      | Backupscreenshots             | ✓ |                                                                                  |
| Traversebackflashflashbulb                   | ✗ |                                                      | Backupimage                   | ✗ |                                                                                  |
| Linecameracleanmirror                        | ⏸ |                                                      | Backupsoftware                | ✓ | ipq-center_bak_2025_04_02_14_17_50                                               |
| Led checking+reflector checking+dome         | ⏸ |                                                      |                               |   |                                                                                  |
| Linecameramechanicalcheck                    | ⏸ |                                                      |                               |   |                                                                                  |
| Linecamerabacklightmechanicalcheckjigs       | ⏸ |                                                      |                               |   |                                                                                  |
| Camera mechanicalalignementtoprint           | ⏸ |                                                      |                               |   |                                                                                  |
| Camera whitecalibration                      | ⏸ |                                                      |                               |   |                                                                                  |

- ✓: Checked, nothing to report / Vérifié, RAS  
✗: Not OK, checked comment / Pas OK, vérifiez commentaires  
⏸: Not actif / Non Actif

Comment(s)

*(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)*

Preventive Maintenance.  
2x8 Flash Bulbs pour la prochaine maintenance + Varnish

Customer signature:

Name:

Date :


BST eltromat FRANCE signature:

Name:

Date :





03-Apr-25 4:57 PM



03-Apr-25 4:44 PM

**ATTACHED PM'S FILE(S)**

|                                                                                   |                                                                                   |                                                                                   |                                                                                   |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| <a href="#">Picture 02042025</a>                                                  | <a href="#">Screenshot 02042025</a>                                               | <a href="#">Iris-camTop-wsc_573</a>                                               | <a href="#">Iris-camBot-wsc_502</a>                                               |
|  |  |  |  |