

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Wipak 231056 M. Eric Ghesquier Drèce des Bois 59166 Bousbecque France +33 6 07 01 64 56 eric.ghesquier@wipak.com
--	---

Preventive reference number	PMREPORT-191_PM755_2024-12-18
Contract number / Numéro de contrat	CM2005031
Contract date:	2023/10/01 -> 2026/09/30
Machine customer name:	Flexotecnica
Assign to:	CouV
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO071462 _ WA0021340
Installation date of material:	2020/12/11

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE01.0-3
PC NAME	21340-IPQ-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Win10Pro
MEMORY RAM	32Go
FREE SPACE ON C	51.7Go/E:39.8Go
FREE SPACE ON D	97Go/F:1.51Go
TEAMVIEWER ID	665008695 / v12
IP ADDRESS EXTERN FOR INTERNET	192.168.1.59
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	17/12/2024 08:30
End time PM:	17/12/2024 12:30

COMMENTS			COMMENTS		
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	✓	
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommend to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2020-12-11 -> 04 YEAR(S)
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	✗	La carte des flash a besoin d'être remplacé	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	✓		Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	✓	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	⏸	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Batterie de l'onduleur remplacé debut 2024.

Customer signature:

Name: **Saussol Benoit**

Date :

BST eltromat FRANCE signature:

Name: **CV**

Date :

8/12/2024 16:58

20/12/2024 14:58