

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	SBE Societe bretonne étiquette ACU531001 M. Nicolas Robert 17 Rue Théodore Botrel 35550 Pipriac France + 33 2 99 34 37 49 atelier.flexo@sbe-etiquettes.fr
--	--

Preventive reference number	PMREPORT-150_PM717_2024-11-07
Contract number / Numéro de contrat	CM2310056
Contract date:	2023/10/01 -> 2026/09/30
Machine customer name:	Jupiter 5
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	Tubescan TS 430 / 325x-0.2778
SN:WA:	34.191
Installation date of material:	

TECHNICAL DATAS

PC MODEL	OptiPlex 3020
PC NAME	TubeScan-PC
ADDITIONAL CAMERA INFO	Tubescan TS 430 / 325x-0.2778
OPERATION SYSTEM	Windows 7 Prodeffionnal / Service Pack 1
MEMORY RAM	8 GB
FREE SPACE ON C	395 / 450 GB
FREE SPACE ON D	-
TEAMVIEWER ID	1 120 388 049 / v15
IP ADDRESS EXTERN FOR INTERNET	DHCP Automatic
ORIGINAL VERSION	6.3.10.52
UPG OR DNG VERSION DURING MAINTENANCE	6.3.20.71

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024x768	Encoder wheel status	✗	Old Wheel with studs. Mist be replaced by Teflon Wheel
View monitor resolution		1680x1050	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	⏸	
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	⏸	
PC's fans ?	✓		Date UPS's batteries exchanged ?		OLD UPS APC NEW UPS EATON recommand to exchange every 5 years.
PC's filter	⏸		Installation date:		-> 00 YEAR(S)
Lens cleaning	✓		UPS communication?	⏸	
Mirror cleaning	✓		Softwareworkflowcommunication	⏸	
Backing or RRB cleaining	✓	Broken & Scratched	Check Teamviewer access	✓	
Lens Focal	✓		Calibration of camera detail & 100%camera	✓	
Camera alignement with printing	✓		Operators instruction ?	⏸	
Check web under camera	✓		Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	⏸	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	⏸				
Kisspoint only with 2 cameras	⏸				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- | | | |
|---|--------------------------------|---|
| ✓ | <input type="text" value="1"/> | ENCODER WHEEL:: 2RDHO234275 |
| | <input type="text"/> | LED Board equipped V40 L=140mm: 1ELLT256485 |
| | <input type="text"/> | LED Board equipped V40 L=160mm: 1ELLT256486 |
| | <input type="text"/> | ENCODER'S SPRING |
| ✓ | <input type="text" value="1"/> | BACKPLATE W/B |

-  : Checked, nothing to report / Vérifié, RAS
 : Not OK, checked comment / Pas OK, vérifiez commentaires
 : Not actif / Non Actif

Comment(s)


(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Maintenance Preventive sur debobineuse Prati. Mise a jour du logiciel.

Customer signature:

Name:

Date :


jeudi 7 novembre 2024 17:22:49

BST eltromat FRANCE signature:

Name:

Date :


jeudi 7 novembre 2024 17:22:27

ATTACHED PM'S FILE(S)

Picture 07112024	Screenshot 07112024
	