

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Helios Périers ACU309170 M. Dupray Sebastien Route de Carentan 50190 Périers France +33 2 33 17 13 13 / +33 6 49 15 30 68 sdupray@helios-imp.com
--	---

Preventive reference number	PMREPORT-232_PM831_2025-03-06
Contract number / Numéro de contrat	CM1912027
Contract date:	2023/02/01 -> 2026/01/31
Machine customer name:	Biva 4 - CI14814
Assign to:	CouV
Material:	REGISTER_R20
Type:	Registrar_20
SN:WA:	WA18133
Installation date of material:	2007/01/01

TECHNICAL DATAS

PC MODEL	C9900-I625 v3.89
PC NAME	Please fill system information
ADDITIONAL CAMERA INFO	Registrar_20
OPERATION SYSTEM	WINDOWS EMBEDDED Standard
MEMORY RAM	2GB
FREE SPACE ON C	Please fill system information
FREE SPACE ON D	
TEAMVIEWER ID	226046601 NEW PC
IP ADDRESS EXTERN FOR INTERNET	DHCP
ORIGINAL VERSION	3.8.0
UPG OR DNG VERSION DURING MAINTENANCE	

Start time PM:	04/03/2025 10:30
End time PM:	04/03/2025 12:30

		COMMENTS			COMMENTS
Check UPS	✓		Check encoder		
Last UPS changed	2025/03/06		Check encoder driving (belt or coupling)		
Check Beckhoff modul	✓				
Check Remote	⏸				
Check Ethercat	✓				
Clean HDD	⏸				
Backup	⏸				
Check IPC fan	✓				
Image IPC	⏸				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

☐	UPS
☐	NEW HDD OR CFAST
☐	NEW IPC
☐	
☐	

<

		COMMENTS			COMMENTS
PU2 traverse	✓		PU2 FIBER1 CALIB	✓	
PU3 traverse	✓		PU2 FIBER2 CALIB	⏸	
PU4 traverse	✓		PU2 COMMENT		
PU5 traverse	✓		PU3 FIBER1 CALIB	✓	
PU6 traverse	✓		PU3 FIBER2 CALIB	⏸	
PU7 traverse	✓		PU3 COMMENT		
PU8 traverse	✓		PU4 FIBER1 CALIB	✓	
PU9 traverse	✓		PU4 FIBER2 CALIB	⏸	
PU10 traverse	⏸		PU4 COMMENT		
PU11 traverse	⏸		PU5 FIBER1 CALIB	✓	
PU12 traverse	⏸		PU5 FIBER2 CALIB	⏸	
PU13 traverse	⏸		PU5 COMMENT		
PU14 traverse	⏸		PU6 FIBER1 CALIB	✓	
TRAVERSE COMMENT			PU6 FIBER2 CALIB	⏸	
			PU6 COMMENT		
			PU7 FIBER1 CALIB	✓	
			PU7 FIBER2 CALIB	⏸	
			PU7 COMMENT		
			PU8 FIBER1 CALIB	✓	
			PU8 FIBER2 CALIB	⏸	
			PU8 COMMENT		
			PU9 FIBER1 CALIB	✓	
			PU9 FIBER2 CALIB	⏸	
			PU9 COMMENT		
			PU10 FIBER1 CALIB	✓	
			PU10 FIBER2 CALIB	⏸	
			PU10 COMMENT		
			PU11 FIBER1 CALIB	⏸	
			PU11 FIBER2 CALIB	⏸	
			PU11 COMMENT		
			PU12 FIBER1 CALIB	⏸	
			PU12 FIBER2 CALIB	⏸	
			PU12 COMMENT		
			PU13 FIBER1 CALIB	⏸	
			PU13 FIBER2 CALIB	⏸	
			PU13 COMMENT		
			PU14 FIBER1 CALIB	⏸	
			PU14 FIBER2 CALIB	⏸	
			PU14 COMMENT		

<

		COMMENTS
PU2 Encoder	✓	
PU3 Encoder	✓	
PU4 Encoder	✓	
PU5 Encoder	✓	
PU6 Encoder	✓	
PU7 Encoder	✓	
PU8 Encoder	✓	
PU9 Encoder	✓	
PU10 Encoder	⏸	
PU11 Encoder	⏸	
PU12 Encoder	⏸	
PU13 Encoder	⏸	
PU14 Encoder	⏸	
Encoder's COMMENT		

- ✓: Checked, nothing to report / Vérifié, RAS
 ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
 ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Il faudrait remplacer les fibres de toutes les unités, voir photos ci-dessous

Customer signature:

Name:


Date :


06/03/2025 14:22

BST eltromat FRANCE signature:

Name:

Date :


07/03/2025 09:38

ATTACHED PM'S FILE(S)

