

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	CCL Package Label - Pharma (Chilly-Mazarin) ACU231910 M. Jean-Charles Campana 20 Avenue Arago 91380 Chilly-Mazarin France +33 7 63 04 72 66 jccampana@cclind.com
--	---

Preventive reference number	PMREPORT-358_PM1002_2025-11-06
Contract number / Numéro de contrat	CM1708005
Contract date:	2022/01/01 -> 2024/12/31
Machine customer name:	Presse 443
Assign to:	DarA
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 430 4K / M2089aC-0.1111
SN:WA:	ASO071778_42.1585
Origin BST France order:	NQ2010049010
Installation date of material:	

TECHNICAL DATAS

PC MODEL	OptiPlex 5070 / Tag G8SSF73
PC NAME	TubeScan421585
ADDITIONAL CAMERA INFO	TubeScan DS 430 4K / M2089aC-0.1111
OPERATION SYSTEM	Windows 10 Pro / 2019
MEMORY RAM	16.0 GB
FREE SPACE ON C	144 / 237 GB
FREE SPACE ON D	-
TEAMVIEWER ID	631 030 314 / v12
IP ADDRESS EXTERN FOR INTERNET	Automatic IP
ORIGINAL VERSION	7.4.44.111
UPG OR DNG VERSION DURING MAINTENANCE	7.4.67.34209

Start time PM:	06/11/2025 08:20
End time PM:	06/11/2025 10:30

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024x768 - 15.5"	Encoder wheel status	✓	Cleaned
View monitor resolution		1920x1080 - 21.5"	Encoder wheel on web?	✗	On the roller
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓		UPS battery exchanged ?	✗	
PC's fans ?	✓		Date UPS's batteries exchanged ?		OLD UPS APC NEW UPS EATON recommand to exchange every 5 years.
PC's filter	⏸		Installation date:		-> 00 YEAR(S)
Lens cleaning	✓	1 camera looking up	UPS communication?	⏸	UPS Communication Lost --> Need to replace Battries or UPS
Mirror cleaning	✓		Softwareworkflowcommunication	⏸	
Backing or RRB cleaining	✓		Check Teamviewer access	✓	631 030 314 / v12
Lens Focal	✓		Calibration of camera detail & 100%camera	⏸	
Camera alignement with printing	✓		Operators instruction ?	⏸	
Check web under camera	✓		Screenshots	✓	On v7.4.67.34209
Height compensator calib	✓		ACRONIS ?	✓	On v7.4.67.34209
Encoder offset calib	✓		Backup application	✓	On v7.4.67.34209
Only with EV- LED calibrations	⏸				
Kisspoint only with 2 cameras	⏸				

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- ✓ ENCODER WHEEL:: 2RDHO234275
- ✓ LED Board equipped V40 L=140mm: 1ELLT256485
- ✓ LED Board equipped V40 L=160mm: 1ELLT256486
- ✓ ENCODER'S SPRING
- ✓ BACKPLATE W/B

- ✓: Checked, nothing to report / Vérifié, RAS
- ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
- ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Preventive Maintenance Completed
- Software upgrade to the latest released version.
- 1 UV LED down
- UPS batteries "End of Life"

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :



06-Nov-25 5:01 PM



06-Nov-25 4:40 PM

ATTACHED PM'S FILE(S)

Picture 06112025	Screenshoot 06112025
	