

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elaxis.group/	Livcer M. Charles de Livonnière 593 avenue Blaise Pascal - Lotissement Anaconda 2 77550 Moissy Cramayel France charles.livonniere@livcer.com
--	---

Preventive reference number	PMREPORT-161_PM752_2024-11-28
Contract number / Numéro de contrat	Please fill system information
Contract date:	
Machine customer name:	P4
Assign to:	RelR
Material:	VIDEO_Tubescan_DS
Type:	TubeScan DS 1100 7200 / M2051dC 0.1667
SN:WA:	ASO089565_50.2649
Origin BST France order:	222010
Installation date of material:	2023/09/12

TECHNICAL DATAS

PC MODEL	Optiplex 7090
PC NAME	TubeScan502649
ADDITIONAL CAMERA INFO	TubeScan DS 1100 7200 / M2051dC 0.1667
OPERATION SYSTEM	Windows 10 Pro / v21H1
MEMORY RAM	32 GB
FREE SPACE ON C	110 / 237 GB
FREE SPACE ON D	Q:\ 1.76 / 1.86 TB
TEAMVIEWER ID	1 011 259 725 / v15
IP ADDRESS EXTERN FOR INTERNET	DHCP Automatic
ORIGINAL VERSION	7.4.61.23532
UPGRADE OR DOWNGRADE VERSION LAST INTERVENTION	7.4.64.29287 from E2211
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	28/11/2024 08:40
End time PM:	28/11/2024 12:00

COMMENTS			COMMENTS		
Touch monitor calibration	✓		Fixation encoder	✓	
Touch monitor resolution		1024X768	Encoder wheel status	✓	Roue codeuse changer
View monitor resolution		2560X1440	Encoder wheel on web?	✓	
Fixation screws of system?	✓		Spring(s) encoder status ?	✓	
Cables status ?	✓		Alarm indicator status ?	✓	
Connectors cameras (well tight?)	✓				
PC's fans ?	✓				
PC's filter	II		Installation date:		2023-09-12
Lens cleaning	✓				
Mirror cleaning	✓		Software workflow communication	✓	
Backing or RRB cleaning	II	Manque backing bar pour stabiliser d'avantage.	Check Teamviewer access	✓	
Lens Focal	✓		Calibration of camera detail & 100% camera	II	
Camera alignment with printing	✓		Operators instruction ?	II	
Check web under camera	✓	En regle general matiere stable, quand il y a passage de gros scotch décalage aperçu a l'écran.	Screenshots	✓	
Height compensator calib	✓		ACRONIS ?	II	
Encoder offset calib	✓		Backup application	✓	
Only with EV- LED calibrations	II				

Kisspoint only with 2 cameras



Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

- | | |
|--------------------------|---|
| ☐ | ENCODER WHEEL:: 2RDHO234275 |
| ☐ | LED Board equipped V40 L=140mm: 1ELLT256485 |
| ☐ | LED Board equipped V40 L=160mm: 1ELLT256486 |
| ☐ | ENCODER'S SPRING |
| ☐ | BACKPLATE W/B |

- ✅: Checked, nothing to report / Vérifié, RAS
❌: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :


28/11/2024 15:13


28/11/2024 15:15