

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Wipak 231056 M. Eric Ghesquier Drèce des Bois 59166 Bousbecque France +33 6 07 01 64 56 eric.ghesquier@wipak.com
--	---

Preventive reference number	PMREPORT-106_PM680_2024-07-15
Contract number / Numéro de contrat	CM2005031
Contract date:	2023/10/01 -> 2026/09/30
Machine customer name:	Flexotecnica
Assign to:	RelR
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO71462 _ WA21340
Installation date of material:	2020/12/11

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE01.0-3
PC NAME	21340-IPQ-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Win10Pro
MEMORY RAM	32Go
FREE SPACE ON C	51.7Go/E:39.8Go
FREE SPACE ON D	97Go/F:1.51Go
TEAMVIEWER ID	665008695 / v12
IP ADDRESS EXTERN FOR INTERNET	192.168.1.59
ORIGINAL VERSION	2.17.9
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

		COMMENTS			COMMENTS
Touchmonitorcalibration	NA		Ipqchecksynchronization	OK	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	OK	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	OK	
Hardwareconditionscrews	OK		Ipqencoderwheelrunningonweb	OK	
Hardwareconditioncables	OK		Alarmstatusindicator	OK	
Hardwareconditionconnectors	OK		Upsbatteryexchanged	NA	
Digitalcheckfan	OK		Upsdatebatteryexchanged		UPS builder recommand to exchange every 4 years.
Digitalreplacefilter	OK		Installation date:		2020-12-11 -> 03 YEAR(S)
Traversecamera	OK		Upscommunicationchecking	OK	MAJ 2.0 faite
Traversecameralenscleaning	OK		Softwareupdate	NA	
Traversewscamerareplaceflashbulb	NA	A changer a la prochaine maintenance.	Version upgraded		
Traversewscameracleanwindows	NA		Softwareipqtcu		1.12
Camerachangefiltercheckfan	OK		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	OK		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	NA		Softwareipqli		1.4.3
Traversewscameracheckcleanmirrorlackercamera	NA		Softwareworkflowcommunication	NA	
Traversewscameracheckzoomirisfocuswscboard	OK		Softwareremote	NA	
Traversewscameracalibrationzoomirisfocus	NA		Operatorinstructions	NA	
Traversebackflash	NA		Backupscreenshots	OK	
Traversebackflashflashbulb	NA		Backupimage	NA	
Linecameracleanmirror	OK		Backupsoftware	OK	
Led checking+reflector checking+dome	OK				
Linecameramechanicalcheck	OK	Vernis impossible a retirer.peut creer des lignes fantomes.			
Linecamerabacklightmechanicalcheckjigs	OK				
Cameramechanicalalignementtoprint	OK				
Camerawhitecalibration	OK				

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name:

Date :

BST eltromat FRANCE signature:

Name:

Date :



2024-07-16T17:00:19+02:00



18/07/2024 17:28