

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	SP Group Soplaril Arras-PLASTIENVASE 231072 M. Mickael Carincotte 1 Rue Claude Bernard 62000 Arras France + 33 3 21 23 68 11 / +33 6 84 64 10 45 mcarincotte@spg-pack.com
--	--

Preventive reference number	PMREPORT-152_PM737_2024-11-13
Contract number / Numéro de contrat	CM1706003
Contract date:	2021/04/01 -> 2024/03/31
Machine customer name:	H12
Assign to:	CouV
Material:	VIDEO_IPQ_Center
Type:	IPQ Center
SN:WA:	ASO025108_WA19450
Installation date of material:	2017/02/15

TECHNICAL DATAS

PC MODEL	IPC-BG-R7910/BSTE01.0
PC NAME	19450IPQ-CENTER
ADDITIONAL CAMERA INFO	IPQ Center
OPERATION SYSTEM	Windows 7 professionnel
MEMORY RAM	32 GB
FREE SPACE ON C	81.2 GB
FREE SPACE ON D	104 GB
TEAMVIEWER ID	879 943 981 / v15
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	2.17.8
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	13/11/2024 15:45
End time PM:	

		COMMENTS			COMMENTS
Touchmonitorcalibration	⏸		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	⏸	
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommend to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2017-02-15
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	⏸	Already changed 6 month ago	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓		Softwareipqwsc		.
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		.
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqili		.
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	⏸	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	⏸		Operatorinstructions	⏸	
Traversebackflash	⏸		Backupscreenshots	✓	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	⏸	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	⏸				
Camera whitecalibration	⏸				

- ✓: Checked, nothing to report / Vérifié, RAS
 ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
 ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name:


Date :

BST eltromat FRANCE signature:

Name:

Date :


14/11/2024 15:46


14/11/2024 15:35

ATTACHED PM'S FILE(S)

filtre matricielle	filtre 100	nettoyage matricielle	nettoyage miroirs 100%	Nettoyage backplate
			