

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Multisac (Chaspuzac) 230116 M. Lionel Januel / M. Pierrick Fourné-Faillard Z.A La Combe – 1 rue des perdrix 43320 Chaspuzac France +33 6 68 09 38 74 / +33 4 71 06 68 68 l.januel@multisac.fr / p.fournet-fayard@multisac.fr
--	---

Preventive reference number	PMREPORT-158_PM746_2024-11-20
Contract number / Numéro de contrat	CM1705001
Contract date:	2023/07/01 -> 2026/06/30
Machine customer name:	Miraflex
Assign to:	CouV
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	WA19380 _ ASO023006
Installation date of material:	2016/12/16

TECHNICAL DATAS

PC MODEL	IPC-BG-R7910/BSTE01.0
PC NAME	19380iPQ-Center1-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	WINDOWS EMBEDDED Standard
MEMORY RAM	32Go
FREE SPACE ON C	80.8
FREE SPACE ON D	104
TEAMVIEWER ID	486 271 966 / v12
IP ADDRESS EXTERN FOR INTERNET	
ORIGINAL VERSION	2.17.2
UPG OR DNG VERSION DURING MAINTENANCE	No software upgrade recommended

Start time PM:	20/11/2024 11:17
End time PM:	

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920x1080	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920x1080	Ipqencoderwheelstatus	✓	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	✓	
Digitalcheckfan	✓		Upsdatebatteryexchanged		2019/05/23
Digitalreplacefilter	✓		Installation date:		2016-12-16
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	⏸	Fait il y a 6 mois lors du precedent préventif	Version upgraded		
Traversewscameracleanwindows	✓		Softwareipqtcu		1.12
Camerachangefiltercheckfan	✓		Softwareipqwsc		1.9.6
Traversewscamerashadowreducingbackplate	✓		Softwareippqps		2.2
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqili		1.4.3
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	✓	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	⏸		Operatorinstructions	✓	
Traversebackflash	⏸		Backupscreenshots	✓	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	⏸	20/11/2024 16:47
Led checking+reflector checking+dome	✓	Remplacement du front-light			
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	✓				

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)

Customer signature:

Name: **Delolme Eric**

Date :

BST eltromat FRANCE signature:

Name: **Coutellier Vivien**

Date :


20/11/2024 16:48


20/11/2024 16:48