

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	Socoplan (Arcade Beauty) ACU230223 M. Franck Bourdon 12 All. De Dissé 79600 Airvault France +33 6 07 48 31 95 / +33 5 49 64 95 01 f.bourdon@arcadebeauty.com
--	---

Preventive reference number	PMREPORT-194_PM764_2024-12-23
Contract number / Numéro de contrat	CM2112043 R2
Contract date:	2024/01/01 -> 2026/12/31
Machine customer name:	DCM 4
Assign to:	CouV
Material:	REGISTER_R20
Type:	Registar_20
SN:WA:	WA0018132
Installation date of material:	2012/09/03

TECHNICAL DATAS

PC MODEL	C6920-1039-0030
PC NAME	registar-18132.
ADDITIONAL CAMERA INFO	Registar_20
OPERATION SYSTEM	Windows XP Service pack 3
MEMORY RAM	956MB
FREE SPACE ON C	1.58/3.68GB
FREE SPACE ON D	72.1/74.5GB
TEAMVIEWER ID	1 673 469 070 / v12
IP ADDRESS EXTERN FOR INTERNET	172.20.11.55 255.255.255.0 172.20.11.254 172.20.10.10 10.217.3.10
ORIGINAL VERSION	2.9.0
UPG OR DNG VERSION DURING MAINTENANCE	

Start time PM:	06/12/2024 08:30
End time PM:	06/12/2024 10:30

COMMENTS			COMMENTS		
Check UPS			Check encoder		
Last UPS changed	2024/12/23		Check encoder driving (belt or coupling)		
Check Beckhoff modul					
Check Remote					
Check Ethercat					
Clean HDD					
Backup					
Check IPC fan					
Image IPC					

Filled quantity needed for quotation:

(if fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

☐	UPS
☐	NEW HDD OR CFAST
☐	NEW IPC
☐	
☐	

<

		COMMENTS			COMMENTS
PU2 traverse	✓		PU2 FIBER1 CALIB	✓	
PU3 traverse	✓		PU2 FIBER2 CALIB	⏸	
PU4 traverse	✓		PU2 COMMENT		
PU5 traverse	✓		PU3 FIBER1 CALIB	✓	
PU6 traverse	✓		PU3 FIBER2 CALIB	⏸	
PU7 traverse	✗		PU3 COMMENT		
PU8 traverse	⏸		PU4 FIBER1 CALIB	✓	
PU9 traverse	⏸		PU4 FIBER2 CALIB	⏸	
PU10 traverse	⏸		PU4 COMMENT		
PU11 traverse	⏸		PU5 FIBER1 CALIB	✓	
PU12 traverse	⏸		PU5 FIBER2 CALIB	⏸	
PU13 traverse	⏸		PU5 COMMENT		
PU14 traverse	⏸		PU6 FIBER1 CALIB	✓	
TRAVERSE COMMENT		Traverse on PU7 is ok but varnish glued	PU6 FIBER2 CALIB	⏸	
			PU6 COMMENT		
			PU7 FIBER1 CALIB	✓	
			PU7 FIBER2 CALIB	⏸	
			PU7 COMMENT		
			PU8 FIBER1 CALIB	✓	
			PU8 FIBER2 CALIB	⏸	
			PU8 COMMENT		
			PU9 FIBER1 CALIB	⏸	
			PU9 FIBER2 CALIB	⏸	
			PU9 COMMENT		
			PU10 FIBER1 CALIB	⏸	
			PU10 FIBER2 CALIB	⏸	
			PU10 COMMENT		
			PU11 FIBER1 CALIB	⏸	
			PU11 FIBER2 CALIB	⏸	
			PU11 COMMENT		
			PU12 FIBER1 CALIB	⏸	
			PU12 FIBER2 CALIB	⏸	
			PU12 COMMENT		
			PU13 FIBER1 CALIB	⏸	
			PU13 FIBER2 CALIB	⏸	
			PU13 COMMENT		
			PU14 FIBER1 CALIB	⏸	
			PU14 FIBER2 CALIB	⏸	
			PU14 COMMENT		

<

		COMMENTS
PU2 Encoder	✓	
PU3 Encoder	✓	
PU4 Encoder	✓	
PU5 Encoder	✓	
PU6 Encoder	✓	
PU7 Encoder	✗	
PU8 Encoder	⏸	
PU9 Encoder	⏸	
PU10 Encoder	⏸	
PU11 Encoder	⏸	
PU12 Encoder	⏸	
PU13 Encoder	⏸	
PU14 Encoder	⏸	
Encoder's COMMENT	PU2-PU6-PU7 Mechanical issue	

- ✓: Checked, nothing to report / Vérifié, RAS
✗: Not OK, checked comment / Pas OK, vérifiez commentaires
⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge navigator or update your navigator)

Customer signature:

Name:

Date :


23/12/2024 17:34

BST eltromat FRANCE signature:

Name:

Date :


23/12/2024 17:35