

BST Eltromat France SARL Impasse de la Noisette - CE402 F-91374 Verrières le Buisson Tél.: +33 1 69 20 07 41 Email: bstfrance@bst.group Web: https://www.bst.elexis.group/	OREP Packaging M. Christophe Mionnet 17 route de Vauzelle 37600 Loches France +33 2 47 91 13 94 christophe.mionnet@orep-packaging.fr
--	--

Preventive reference number	PMREPORT-236_PM842_2025-03-12
Contract number / Numéro de contrat	CM2306054
Contract date:	2023/07/01 -> 2026/06/30
Machine customer name:	F8
Assign to:	CouV
Material:	VIDEO_IPQ_Center
Type:	iPQ Center
SN:WA:	ASO079110_WA21625
Origin BST France order:	213312
Installation date of material:	2022/03/11

TECHNICAL DATAS

PC MODEL	IPC-BG-BKA-BSTE03.0-7
PC NAME	21625-IPQ-1
ADDITIONAL CAMERA INFO	iPQ Center
OPERATION SYSTEM	Windows 10 Enterprise LTSC - v1809
MEMORY RAM	64 GB
FREE SPACE ON C	37.9 / 75.0 GB
FREE SPACE ON D	F:\ 7.13 / 7.27 TB
TEAMVIEWER ID	437 068 597 / v15
IP ADDRESS EXTERN FOR INTERNET	Adresse IP : 192.168.10.37 Masque de sous-réseau : 255.255.255.0 Passerelle par défaut : 192.168.10.60 Serveur DNS privilégié : 194.2.0.20 Serveur DNS alternatif : 194.2.0.50
ORIGINAL VERSION	2.17.6
UPG OR DNG VERSION DURING MAINTENANCE	3.2.5

Start time PM:	12/03/2025 12:13
End time PM:	

		COMMENTS			COMMENTS
Touchmonitorcalibration	✓		Ipqchecksynchronization	✓	
Pcscreenresolutiontouch		1920X1080 Touch	Ipqencoderwheelfixing	✓	
Pcscreenresolutionview		1920X1080 Full View+43"	Ipqencoderwheelstatus	⏸	
Hardwareconditionscrews	✓		Ipqencoderwheelrunningonweb	✓	
Hardwareconditioncables	✓		Alarmstatusindicator	✓	
Hardwareconditionconnectors	✓		Upsbatteryexchanged	✓	
Digitalcheckfan	✓		Upsdatebatteryexchanged		UPS builder recommend to exchange every 4 years.
Digitalreplacefilter	✓		Installation date:		2022-03-11 -> 03 YEAR(S)
Traversecamera	✓		Upscommunicationchecking	✓	
Traversecameralenscleaning	✓		Softwareupdate	⏸	
Traversewscamerareplaceflashbulb	⏸		Version upgraded		3.2.5
Traversewscameracleanwindows	✓		Softwareipqtcu		1.14
Camerachangefiltercheckfan	✓		Softwareipqwsc		1.9.7
Traversewscamerashadowreducingbackplate	✓		Softwareipqpps		2.2
Traversewscameracheckflashbulblackerflash	⏸		Softwareipqili		1.6.1
Traversewscameracheckcleanmirrorlackercamera	⏸		Softwareworkflowcommunication	⏸	
Traversewscameracheckzoomirisfocuswscboard	✓		Softwareremote	✓	
Traversewscameracalibrationzoomirisfocus	⏸		Operatorinstructions	✓	
Traversebackflash	⏸		Backupscreenshots	✓	
Traversebackflashflashbulb	⏸		Backupimage	⏸	
Linecameracleanmirror	✓		Backupsoftware	⏸	
Led checking+reflector checking+dome	✓				
Linecameramechanicalcheck	✓				
Linecamerabacklightmechanicalcheckjigs	✓				
Camera mechanicalalignementtoprint	✓				
Camera whitecalibration	⏸				

- ✓: Checked, nothing to report / Vérifié, RAS
 ✗: Not OK, checked comment / Pas OK, vérifiez commentaires
 ⏸: Not actif / Non Actif

Comment(s)

(If fields are not visible please open PDF file with Google chrome or Microsoft edge nagivator or update your navigator)


Customer signature:

Name: **Mionnet Christophe**
 Date :

BST eltromat FRANCE signature:

Name: **Coutellier Vivien**
 Date :


 12/03/2025 16:51


 12/03/2025 16:51